

Bid Opportunity 404-2009 ADDENDUM 1

ISSUED:

BY:

PROVINCE OF MANITOBA/CITY OF WINNIPEG: MCPHILLIPS STREET WIDENING - SELKIRK AVENUE TO CPR UNDERPASS - WIDENING, CONCRETE REPAIRS AND ASPHALT RESURFACING

> June 16, 2009 Stantec Consulting Ltd.

TELEPHONE NO. (204) 489-5900

URGENT

PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE BID OPPORTUNITY

THIS ADDENDUM SHALL BE INCORPORATED INTO THE BID OPPORTUNITY AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 10 of Form A: Bid may render your Bid non-responsive.

PART A - BID SUBMISSION

Replace: Bid Opportunity 404-2009 Bid Submission with Bid Opportunity 404-2009 Addendum 1 – Bid Submission. The following is a summary of changes incorporated in the replacement Bid Submission:

Form B(R1):	Item A.51 i) – Added a decimal place.
	Deleted Item A.76 i) American Elm.
	Deleted Item A.77 Two Year Extended Maintenance.
	Item A.82 ii) – Added "Jacking Method" to Description.
Form G2(R1):	The Standby Letter of Credit expiry date changed from August 17, 2009 to August 18, 2009.

PART B – BIDDING PROCEDURES

Revise: B2.1 to read: The Submission Deadline is 12:00 noon Winnipeg time, June 19, 2009.

PART D – SUPPLEMENTAL CONDITIONS

Delete: D22.1 c) Extended Two Year Maintenance

PART E – SPECIFICATIONS

Add:	E2.2	Additional borehole logs are located in 404-2009_Addendum_1_Additional_Geotechnical _Report.pdf. Test hole 1 is located approximately 10m north of of the track near the alignment of the steel casing pipe and test hole 2 was located approximately 10m south of the track near the alignment of the steel casing pipe.
Add:	E22.4.2	The location of the trenchless shafts shall be no less than 10.0m from the centreline of the rail. The location of the shafts shall be approved by the Contract Administrator prior to construction of the shaft.
Delete:	E28.	Extended Maintenance.