

APPENDIX B
BUILDING CONDITION ASSESSMENT REPORT

prepared by Crosier Kilgour & Partners Ltd.

dated June 14, 2019

REPORT FOR:

St. James Civic Centre 2055 Ness Avenue Building Condition Assessment

Submitted to: City of Winnipeg
Planning, Property, and Development Department
Accommodation Services

Attention: Mr. Greg Kucel

Date: June 14, 2019 (Revised 2019-09-30)

Submitted by: Crosier Kilgour & Partners Ltd.
300-275 Carlton Street
Winnipeg, Manitoba R3C 5R6
Phone: 204.943.7501 Fax: 204.943.7507
Website: www.ckpeng.com

Contact: Mr. Derek J. Mizak, P.Eng.

Our File No. 2019-0374



Crosier Kilgour & Partners Ltd.™

CONSULTING STRUCTURAL ENGINEERS



Table of Contents

Executive Summary	1
1. Introduction.....	2
1.1 Limitations	2
1.2 Scope of Investigation	2
1.3 Priority of Recommendations	3
1.4 Opinion of Probable Construction Costs.....	3
2. Property Description.....	4
2.1 General.....	4
2.2 Building Structure	5
2.2.1 Recreation Centre (RC-22) and Indoor Swimming Pool (PI-05)	5
2.2.2 Arena (AR-03).....	6
2.3 Building Envelope and Cladding	6
2.3.1 Recreation Centre (RC-22).....	6
2.3.2 Indoor Swimming Pool (PI-05).....	6
2.3.3 Arena (AR-03).....	6
2.4 Roofing.....	7
2.4.1 Recreation Centre (RC-22).....	7
2.4.2 Indoor Swimming Pool (PI-05).....	8
2.4.3 Arena (AR-03).....	8
2.5 Pool Arena (AR-03) Mechanical Systems.....	8
2.5.1 Heating Systems.....	8
2.5.2 Pool and Domestic Water Systems	8
2.5.3 HVAC Systems	9
3. Recreation Centre (RC-22)	13
3.1 Exterior	13
3.1.1 Pavement, Sidewalks, Structures	13
3.1.2 Grading	14
3.2 Structural	14
3.2.1 Basement/Crawlspace	14
3.2.2 Main Floor Structure and Common Areas	19
3.2.3 Mezzanine.....	20
3.2.4 Roof (Exterior).....	22
3.3 Building Envelope.....	22
3.3.1 Walls and Cladding	22
3.3.2 Glazing.....	34
3.3.3 Roof	35



4.	Indoor Swimming Pool (PI-05)	37
4.1	Exterior	37
4.1.1	Pavement, Sidewalks, Structures	37
4.1.2	Grading	38
4.2	Structural	39
4.2.1	Basement/Crawlspace	39
4.2.2	Swimming Pool and Pool Deck	42
4.2.3	Main Floor Structure and Common Areas	44
4.2.4	Building Superstructure	46
4.2.5	Roof (Exterior)	48
4.3	Building Envelope	49
4.3.1	Walls and Cladding	49
4.3.2	Glazing	53
4.3.3	Roofing	62
4.4	Mechanical	66
4.4.1	HVAC	66
5.	Arena (AR-03)	71
5.1	Exterior	71
5.1.1	Pavement, Sidewalks, Structures	71
5.2	Structural	71
5.2.1	Basement/Crawlspace	71
5.3	Building Envelope	79
5.3.1	Walls and Cladding	79
5.3.2	Roof	81
6.	Estimates of Probable Construction Costs	85
7.	Closure	88
Appendix A	Thermographic Report - Recreation Centre (RC-22)	
Appendix B	Thermographic Report - Indoor Swimming Pool (PI-05)	



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Executive Summary

At the request of the City of Winnipeg Planning Property & Development Department, a structural, building envelope, and mechanical systems assessment of the St. James Civic Centre was completed by Crosier Kilgour & Partners and Epp Siepman personnel.

The investigation identified two items requiring repair within 3 months to address specific safety concerns including replacement or upgrading of the existing mezzanine guardrail and repairs to the existing fixed access roof ladders.

Short term priorities include structural concrete repairs and crack injection of the pool tank, replacement of the roof membrane, mechanical repairs to the pool exhaust and ductwork, repairs to exterior pavements and landings, and re-grading of landscaping. A structural assessment of the pool tank is also recommended.

Medium term priorities include replacement of the pool deck and tank tile and waterproofing; re-cladding of the west elevation wall; replacement of windows; replacement of entrance doors and curtain wall; replacement of the HVAC and boilers and re-paving the existing driveway.

Long term priorities include remediation of the crawlspace; recladding of the pool walls; and replacement of the air handler.

Other long-term considerations and/or optional improvements include repairs to the lower level floor slabs; upgrading existing controls, and repair/replacement of fans and mechanical units.

Category	Estimate
Total Required Repairs (within 3 months)	\$20,000
Total Short-Term Recommendations (within 1 year)	\$2,202,000
Total Medium-Term Recommendations (Year 1 to 5)	\$892,000
Total Long-Term Recommendations (Year 5 to 10)	\$465,000
Long Term Considerations/Recommended Improvements (not time critical)	\$2,444,000
Total of All Recommendations	\$6,023,000



1. Introduction

At the request of the City of Winnipeg Planning Property & Development Department, a structural, building envelope, and mechanical systems assessment of the St. James Civic Centre Pool was completed by Crosier Kilgour & Partners and Epp Siepman personnel. The purpose of the investigation was to provide an opinion as to the current condition of the structure, cladding, windows and roofing, identify areas of distress, and provide recommendations aimed at extending the service life of the structure and building envelope components.

The following report details the review methods utilized, problem background, and provides a summary of our observations and findings, as well as opinions regarding the condition of the structure and building envelope. Recommended repairs and estimates of budget construction costs are also provided where appropriate.

1.1 Limitations

Our assessment is based on a visual examination of representative portions of the building under review which were easily visible, exposed, and could be examined. We cannot warrant any different conditions that may exist, but which are covered by finishes, or other materials, or not accessible at the time of the site visit. It should be further acknowledged that our foundation evaluation is based on the present condition only and that we cannot guarantee that future foundation movements will not occur due to movements in the subsoil.

This report has been prepared for the sole benefit of City of Winnipeg. The report may not be reviewed, referred to, or relied upon by any other person or entity without the prior written permission of Crosier Kilgour & Partners Ltd. and City of Winnipeg.

1.2 Scope of Investigation

The intent of this project is to complete a non-destructive condition assessment of the structure and building envelope, and provide recommendations for immediate, short, and long-term repairs.

The investigation included a review of available documentation such as original construction drawings, engineering reports, roofing reports, maintenance reports, and discussions with personnel familiar with the structures.

A visual review of representative portions of the building structure, envelope, and roof(s) which were exposed and readily accessible including common public areas such as entrance foyer, corridors, stairwells, and representative non-public areas such as accessible crawlspaces, and mechanical rooms.

The results of our investigation are summarized in this final report including recommendations, and a Class 4 (-30% to +60%) estimate of probable construction costs for the property.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

1.3 Priority of Recommendations

All recommendations for building systems or components identified in the following sections have been assigned a priority based on the following criteria for the purposes of scheduling and budgeting in accordance with the following:

- Required Repairs (within 3 months) – Repairs necessary to address specific safety issues. Repairs required within 3 months.
- Short Term Recommendations (within 1 year) – High priority for repairs/maintenance including code and regulatory issues.
- Medium Term (Year 1 to 5) – Repairs required to address ongoing or low-risk deterioration, replacement of end of service-life building components.
- Long Term (Year 5 to 10) – Repairs required to address ongoing or low-risk deterioration, replacement of end of service-life building components.
- Long Term Considerations/Recommended Improvements (not time critical) – Optional work including recommended improvements presented for future consideration and planning.
- Maintenance (ongoing) – Repairs required to address ongoing, or routine maintenance.

1.4 Opinion of Probable Construction Costs

Accurate estimation of construction costs for remediation projects is difficult to provide because of the inherent number of variables associated with working on an existing structure. Hidden conditions inevitably exist which can result in increases in the overall cost of repairs. Based on the level of investigation and available information, the budget is considered a Class 4 (-30% to +60%) estimate in accordance with the city of Winnipeg budget classification system. The cost estimate is a preliminary estimate used in developing long term capital plans and for preliminary discussion of proposed capital projects.



2. Property Description

The following description is based on a review of the existing architectural and structural drawings, and visual observations made during the site reviews. A satellite image of the site is shown in Figure 1 below.

The following drawings were available for review:

- Architectural drawings A1 through A21 by Zunic & Sobkowich Architects and dated 1965.
- Structural drawings S1 through S9 by Crosier & Greenberg Consulting Engineers and dated 1965.

Figure 1 – Site Plan



2.1 General

The St James Civic Centre Complex is located at 2055 Ness Avenue, Winnipeg, Manitoba, and consists of three building assets, an Indoor Swimming Pool (PI-05), an Ice Arena (AR-03) and a Recreation Centre (RC-22). The total area of this multi-use recreational facility is 98,635 square feet



and the original building components were constructed in 1966. The arena opened January 22, 1966, and the Pool and Auditorium opened April 9, 1966. There have been several additions and alterations made to the building since its original construction. The site has a flat topography and the building is surrounded by hard-surface paved driveways, grassed areas and landscaped areas. The scope of this investigation includes a review of the Recreation Centre (RC-22) and a summary of the previously completed assessments of the Ice Arena (AR-03) and swimming pool (PI-05).

2.2 Building Structure

2.2.1 Recreation Centre (RC-22) and Indoor Swimming Pool (PI-05)

The pool and auditorium are a two-storey structure with a partial basement and crawlspace. The roof over the pool and auditorium consist of 24" deep precast concrete single-tee "monowing" slabs spaced at 3'-0" on-center. The single-tee slabs span in the north-south direction and are supported on each end of the panel by steel hangers embedded in the web of the tee, known in the precast industry as Cazaly Hangers. The hangers are welded to steel angles embedded in the side of the 10" x 24" concrete beams. The design also relies on steel reinforcing bars welded to the hanger plates to transfer the vertical loads into the beam. The 10" x 24" concrete beams are supported on cast-in-place concrete columns.

The high roof over the second floor is constructed of a 1-1/2" – 22-gauge steel decking supported on 26" short span steel joists spaced at approximately 6'-0" on-center. The roof joists span in the north-south direction to steel beams supported on steel columns.

The low roof over the main floor is constructed of a 1-1/2" – 22-gauge steel decking supported on 20" short span steel joists spaced at approximately 6'-0" on-center. The roof joists span in the north-south direction to 8" concrete masonry unit (CMU) walls.

The second-floor structure consists of a 6-1/2" cast-in-place concrete slab spanning in the north-south direction to 10" x 24" concrete beams supported on concrete columns.

The main floor structure in the common spaces is constructed of conventionally reinforced cast-in-place concrete slabs. The slab construction varies with location but typically consists of either a 6" thick two-way spanning or a 6-1/2" thick one-way spanning slab.

The pool deck and tank are constructed of conventionally reinforced cast-in-place concrete. The pool deck is typically a 6" thick concrete slab spanning between the pool tank wall and exterior foundation wall. The pool tank is constructed of a 9" thick conventionally reinforced two-way spanning concrete slab. The slab is supported directly on the concrete pile foundation. The tank walls vary in thickness. The upper portion is 10" thick and increases to 18" thick in the deep end of the tank.

The lower level includes occupied spaces for mechanical and electrical services, as well as storage and staff rooms. The basement floor slab consists of a 6" slab on gravel fill and 4 mil polyethylene vapour retarder.

The remaining basement area is unfinished crawlspace. Drawings do not indicate if a vapour retarder was included in the original design however evidence of a polyethylene vapour retarder was observed during the site visits.



The building is founded on a deep foundation system consisting of cast-in-place concrete end-bearing piles of varying sizes and depths.

2.2.2 Arena (AR-03)

The arena roof framing consists of 3" x 22-gauge steel decking supported on long span Pratt-style steel trusses. The steel trusses provide span in the east-west direction to W-section steel columns which are supported on 10" x 20" cast-in-place concrete columns that extend down to 28" diameter cast-in-place concrete caissons.

The main floor of the arena area, which includes the ice rink, dressing rooms, and viewing stands, is structurally supported and typically consists of a 6" thick cast-in-place structural concrete slabs supported on cast-in-place concrete beams and foundation walls. A crawlspace is provided throughout the arena area. Foundations for the main floor structure typically consists of 16" spread-bore piles below dressing rooms and viewing stands, and 18" diameter straight shaft piles to refusal below the ice rink.

The viewing stands are constructed of pre-cast concrete.

The exterior walls consist of concrete masonry unit (CMU) walls with loose-fill insulation in the cores from grade to the top of the viewing stands. Above the viewing stands the typical wall construction is insulated metal panel.

2.3 Building Envelope and Cladding

2.3.1 Recreation Centre (RC-22)

The south and east elevation wall assembly are original to the building and generally consists of from interior to exterior, plaster on metal lath, 1½" rigid insulation, cavity space, and 2" precast concrete panels.

On the north elevation adjacent to the low roof, the exterior wall consists of from interior to exterior, plaster on metal lath on steel stud framing, cavity, 1 1/2" rigid insulation, on 6" concrete block walls.

2.3.2 Indoor Swimming Pool (PI-05)

A building envelope retrofit at the pool area was completed as part of a previous renovation. The wall construction at the South end portion of West elevation consists of metal panel with steel girts, air space, rigid insulation, air barrier membrane, and existing concrete block back-up. Along the remainder of the West elevation and North elevation (west side), existing wall construction consists of 4" masonry face block, air space, rigid insulation, air barrier membrane, and existing concrete block back-up.

2.3.3 Arena (AR-03)

The typical exterior wall system for the arena consists of load bearing concrete block along the lower eight feet, which in turn is supported on a continuous cast-in-place concrete foundation wall. The superstructure, or upper elevation, consists of an insulated metal liner panel assembly, incorporating exterior metal cladding.



The concrete block walls are called up with insulation fill in the cores, which provides a nominal level of thermal resistance. Technically, the system does not incorporate an air barrier and the interior layers of paint likely provide vapour diffusion control. In locker areas however, where drywall and batt insulation has been provided, the drywall would provide the air leakage control but is discontinuous at all terminations.

The superstructure utilizes the insulated metal panel assembly; air barrier and vapour diffusion control are provided by the metal liner panel. It is difficult to determine the thickness of the insulation from the drawings, however, it appears to be 1.5" semi-rigid fiberglass.

2.4 Roofing

St James Civic Center complex consists of 12 roof facets. Figure 2 includes roof identification numbers for ease of discussion. Throughout the complex there are 3 types of roof system in various conditions. Referring to the complex photo the following roof facet consists of the noted system type.

Figure 2 –Roof Plan



Roof Facet, R1, R5, R7, R8, R10, and R12 the existing is a 4-ply asphaltic roof system. The assembly consists of a gravel coat, asphaltic 4 ply felt paper, fiberboard, and 2-ply organic felt vapor barrier. On R1, R5, R7, R8, and R12 the slope on all roofs are under 0.1% approximately .2/12. R10 roof, the existing slope is approximately 3/12.

The following 3 roof facets, R3, and R4 the cover consists of a typical standing seam metal roof panel system. Presently the slope is adequate to provide positive water runoff. The remaining roof facets R2, R6, R9, and R11 consists of an SBS insulated modified bitumen roof system. The slope on all roof facets average over 2% which is very acceptable.

2.4.1 Recreation Centre (RC-22)

The recreation centre consists of 3 roof facets and is approximately 8,800 square feet in total. The existing roof facets are a typical 4-ply asphaltic roof system. The assembly consists of a



gravel ballast, asphaltic 4 ply felt paper, fiberboard, and 2-ply organic felt vapor barrier. On the 2 adjacent roof facets the slope on both are under 0.1% approximately 0.2/12. The main recreation centre roof, the existing slope is approximately 3/12.

- Recreation Centre R-10 (4-ply) = 6,200 square feet total
- Adjacent sections R-7 & R-8 (4-ply) = 2,000 square feet total

2.4.2 Indoor Swimming Pool (PI-05)

St James Civic center pool roof consists of two roof facets and each facet comprises of two different roof systems. The main pool roof, and locker room lower roof. The following notes square footage for each roof facet.

- Main pool roof R-9 & R-11 (2-ply) = 6,200 square feet total area
- Lower roof R-4, R-5, & R-12 (4-ply) = 3,100 square feet total area

2.4.3 Arena (AR-03)

The arena roof system is the original asphalt and gravel assembly. The assembly consists of a gravel ballast, asphaltic 4 ply felt paper, fiberboard, and 2-ply organic felt vapor barrier. The arena roof measured slope is under 0.1% approximately 0.2/12. R10 roof. The north west adjacent building is a typical metal roof cladding and is uninsulated. On the west end of the arena an outbuilding roof is an insulated SBS modified bitumen roof type.

- Arena roof R-1& R-6 (4-ply) = 31,000 square feet total
- N/W outbuilding R-3 (metal) = 500 square feet total
- West outbuilding R-2 (SBS) = 800 square feet total

2.5 Pool Arena (AR-03) Mechanical Systems

2.5.1 Heating Systems

Two hot water boilers are the main heating source for the civic centre including the pool area HVAC systems. A separate hot water boiler provides heat for the pool water and domestic hot water needs. All boilers are located in the basement mechanical room. They are original equipment and though old, still operate somewhat reliably. The HVAC boilers are Sunnyday 66 Model: A 66-W-11, 2500mbh input, 2000mbh output.

2.5.2 Pool and Domestic Water Systems

The domestic hot water boiler provides heat for the domestic water via a heat exchanger. Domestic water is stored in two large tanks and fed to the building fixtures. Pool pumps draw the pool water from the tanks and pump through the filtration and treatment systems to feed the pools. The domestic water boiler is a Cleaver Brooks XBG2-1250, 1250mbh input, 1000mbh output.



Photograph 2.5.2-1: Domestic Water Boiler



Photograph 2.5.2-2: Domestic Water Storage Tanks



2.5.3 HVAC Systems

.1 Pool Deck Air Handling Unit (AHU-1)

Unit AHU-1 is used to provide temperature control for the pool area. It is located in the basement and serves the pool deck via distribution ductwork in the crawlspace below the pool deck. Supply grilles around the perimeter provide supply air up through the floor at the exterior walls. This unit is a heat only unit utilizing a pumped hot water coil. It draws air



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

down from the fresh air unit located on the roof. The ductwork up to the roof is exposed in the pool supply/storage room.

Photograph 2.4.4.1-1: Air Handling Unit, AHU-1



.2 Fresh Air Unit (AHU-2)

The fresh air unit (AHU-2) is located on the roof. It was designed as a combination heating and cooling unit. AHU-2 draws return air from the pool deck and mixes it with fresh air to provide mixed air to the pool unit AHU-1. The exhaust ductwork is exposed in the change room ceiling space and has been painted to help withstand the humid, corrosive environment.

Photograph 2.5.3.2-1: Pool Fresh Air Unit AHU-2





.3 Boiler Room Unit (AHU-3)

MUA-3 is a gas fired unit that provides conditioning for the boiler room in the basement.

Photograph 2.5.3.3-1: AHU-3 Boiler Room Unit



.4 Change Room Exhaust

The change room exhaust fans are original equipment to the building. They are axial type fans suspended within the change room ceiling space.

Photograph 2.5.3.4-1: Change Room Exhaust Fan, typical for each change room.



.5 Weight Room (AHU-4)

The unit serving the weight room is a Lennox gas fired packaged roof top unit, with d/x cooling. It is controlled by a programmable thermostat mounted in the weight room space.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 2.5.3.5-1: Weight Room air handling unit, AHU-4





3. Recreation Centre (RC-22)

The following sections summarize the significant findings, recommendations, and estimates of probable construction costs.

3.1 Exterior

3.1.1 Pavement, Sidewalks, Structures

- .1 The asphalt paving along the east elevation is in fair condition. Localized cracking was visible primarily within the parking stalls along the.

Recommendation 3.1.1.1-1: Complete localized repairs to existing asphalt paving.

Estimated Cost: \$15,000

Priority: Medium Term, recommended within 1 to 5 years.

- .2 The main entrance has asphalt paving leading up to a concrete landing. A slight tripping hazard exists at the transition from the asphalt pavement to concrete landing due to differential settlement. Concrete repairs are required at the edge of landing. Previous repairs have been completed. Recommend repairs in the short term.

Photograph 3.1.1.2-1: Partial view of entrance landing/pavement joint.



Recommendation 3.1.1.2-1: Complete localized repairs to address concrete deterioration and tripping hazard at transition.

Estimated Cost: \$18,000

Priority: Short Term, recommended within 1 year.



3.1.2 Grading

- .1 The asphalt pavement on east side is typically well sloped away from building.
- .2 Landscaping on the south and east elevations are finished with either planting beds or sod. The grade appears to slope away from the building.

Photograph 3.1.2.1-1: Partial view of east elevation grading.



3.2 Structural

3.2.1 Basement/Crawlspace

- .1 A crawlspace is located below the auditorium, main entrance lobby, and swimming pool. No evidence of a vapour retarder was observed on the crawlspace floor (Photograph 3.2.1.1-1). The exposed soil within the crawlspace appeared to be dry. At some locations the grade has slumped exposing the tops of the piles (Photograph 3.2.1.1-2). No evidence of deterioration on the piles was observed. Refer also to Section 4.2.1.1

Photograph 3.2.1.1-1: Unfinished crawlspace floor show exposed soil.





Photograph 3.2.1.1-2: Unfinished crawlspace floor show exposed soil.



Recommendation 3.2.1.1-1: The crawlspace does not have a functioning vapour barrier. Remediation of the crawlspace is recommended including grading of the existing soil to direct water away from structural members, installation of a new drainage system and sump pits (if required, see mechanical), and installation of a vapour retarder and sand cover. Installation of new sub-surface drainage, vapour barrier, and sand cover is recommended within 5 years.

Estimated Cost: \$350,000

Priority: Long Term, recommended within 5 to 10 years.

- .2 Water staining was observed on the ceiling tiles in the basement boardroom. The water staining appears to be related to mechanical systems.

Photograph 3.2.1.2-1: Water staining on ceiling tiles.





- .3 A large crack was visible on the south face of the north wall within the storage room (former gun range). The crack extends for the entire length of the wall (Photographs 3.2.1.3-1 and 3.2.1.3-2). At its widest point the crack is estimated to be greater than 3 mm in width (Photograph 3.2.1.3-3). Evidence of displacement along the crack was also observed (Photograph 3.2.1.3-4).

Photograph 3.2.1.3-1: Cracking in north wall (east end)



Photograph 3.2.1.3-2: Cracking in north wall (centre).





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 3.2.1.3-3: Close-up of crack.



Photograph 3.2.1.3-4: Evidence of displacement in wall.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

A portion of the north side of the wall was accessed via the crawlspace. No evidence of cracking was observed (Photograph 3.2.1.3-5).

Photograph 3.2.1.3-4: Evidence of displacement in wall.



The cause(s) of the cracking could not be determined but is consistent with overloading in flexure, possibly due to soil pressure. A review of the original drawings indicates that the wall construction consists of a 10" concrete wall reinforced with 2 - #8 horizontal bars top and bottom; #4 bars at 24" on-centre vertical inside face; and #3 bars at 18" on-centre horizontal inside face.

Recommendation 3.2.1.3-1: It is anticipated that structural repairs will be required to address the cracking in the wall. However, since the cause of the cracking has not been determined, further investigation and analysis is required in the short term to determine causes. The investigation would include confirmation of existing reinforcing detailing and a structural analysis of the wall based on existing loading conditions.

Estimated Cost: \$5,000

Priority: Short Term, recommended within 1 year.



3.2.2 Main Floor Structure and Common Areas

- .1 Leakage visible along transition from lobby roof to auditorium roof. No obvious deterioration to the structural components was observed. Refer to Section 3.3.3 for roofing recommendations.

Photograph 3.2.2.2-1: Leakage visible along transition from lobby roof to auditorium roof.



- .2 The precast roof tees are covered with a textured finish which is preventing visual inspection of the tee connections. No obvious evidence of structural distress of the tees was observed.

Photograph 3.2.2.3-1: Precast concrete roof tees.





- .3 The existing steel roof framing was visible below the low roof. The steel deck and joists are in good condition.

Photograph 3.2.2.4-1: Steel joists at low roof.



3.2.3 Mezzanine

- .1 The steel roof structure is exposed within the daycare located on the mezzanine level. The steel deck and joists are in good condition.


Photograph 3.2.3.1-1: Steel joists at mezzanine roof.



- .2 Horizontal cracking was observed in the south concrete block bearing wall. The cause of the cracking could not be determined. Repointing of the crack is recommended.



Photograph 3.2.2.2-1: Horizontal crack in masonry wall.




Recommendation 3.2.2.2-1: Repoint horizontal crack in concrete block wall.

Estimated Cost: \$3,000

Priority: Medium Term, recommended within 1 to 5 years.

- .3 Evidence of leakage was visible along west wall in the west stairwell. Refer to Section 3.3.3 for roofing recommendations. Step cracking is also visible in southwest corner.

Photograph 3.2.2.1-1: Evidence of leak in ceiling tile at east exit door.



Recommendation 3.2.2.3-1: Repoint step cracking in concrete block wall.

Estimated Cost: \$4,000

Priority: Medium Term, recommended within 1 to 5 years.



3.2.4 Roof (Exterior)

- .1 Access to roof is provided by way of fixed access ladders on the west elevation (refer to 4.2.5.1). The access ladder from east roof to south roof is loose and needs repair. Similar conditions were observed at the ladder from the west roof (refer to 4.2.5.2)

Recommendation 3.2.4.2-1: Repair loose connection at low access ladders to south roof.

Estimated Cost: \$5,000

Priority: Required Repairs (within 3 months)

- .2 The existing concrete entrance canopy over the south entrance is in good condition. Localized hammer soundings were completed and did not reveal any evidence of delamination or deterioration of the concrete

3.3 Building Envelope

3.3.1 Walls and Cladding

- .1 The south and east elevation of the auditorium are clad with pre-cast concrete panels. The panels appear to be finished with an elastomeric coating which is in good condition. The precast panels are in good overall condition with the exception of a few localized cracks (Photographs 3.3.1.1-1 and 3.3.1.1-2) and areas of physical damage (Photograph 3.3.1.1-3). The cause of the damage could not be determined but may be related to landscaping equipment.

Photograph 3.3.1.1-1: Crack at top of precast concrete column.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 3.3.1.1-2: Crack at top of precast concrete column.



Photograph 3.3.1.1-3: Spalled corner of pre-cast concrete column.



Recommendation 3.3.1.1-1: Localized concrete repairs are recommended to address localized areas of concrete damage. Repairs will vary depending on location but could include localized patching of delaminated or spalled concrete; epoxy injection of cracks; and/or sealing of cracks with an elastomeric sealant. Repairs should include replacement of the elastomeric wall coating.

Estimated Cost: \$15,000

Priority: Short Term, recommended within 1 year.



- .2 The joint in the precast panels are sealed with an elastomeric sealant. From grade, the joints appear to be in good condition, with exception of the joint at the south east corner, which is cracking and debonding at points along its length, specifically at the top of the wall below the parapet cap.

Recommendation 3.3.1.2-1: Conduct localized repairs to precast joint sealants.

Estimated Cost: \$3,000

Priority: Short Term, recommended within 1 year.

Photograph 3.3.1.2-1: Debonded sealant joint.




- .3 Evidence of thermal bridging and air leakage at the parapet level of the precast concrete panels was observed during the thermographic scan in Appendix A (Photographs 3.3.1.3-1 and 3.3.1.3-2) indicating discontinuities at the roof wall interface. A review of the original building drawings suggests that a path for air leakage likely exists between the precast wall and roof panels. Random thermal anomalies like those shown in Photograph 3.3.1.3-1 and 3.3.1.3-2 indicate that air leakage is occurring. Mechanical pressurization and stack effect will act to force the interior air up through the wall and roof assemblies. The lack of




an effective air barrier at the junction of the roof and wall assemblies allows the air to escape and travel upward along the parapet. Thermal bridging at the precast concrete panels is expected in this type of construction. The fins of the precast concrete panels act as radiators and readily transfer heat from the wall assembly to the exterior. While the continuous insulation on the interior side of the wall assembly aids in reducing the thermal transfer, the mass of the concrete fins encourages heat flow to the exterior.

Photograph 3.3.1.3-1: Example of air leakage at the parapet level of the precast concrete wall panels, likely caused by a discontinuity at the roof wall interface.



Photograph 3.3.1.3-2: View of elevation showing the typical thermal bridging pattern. Additionally, air leakage is visible at the top of the panels likely from the roof wall interface.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Recommendation 3.3.1.3-1: Additional investigation of the building envelope assembly is required to confirm the observations contained in this report.

Estimated Cost: \$25,000

Priority: Medium Term, recommended within 1 to 5 years.

Recommendation 3.3.1.3-2: The design of the existing wall system is prone to air leakage and thermal bridging. Over the long term, consideration should be given to removal and replacement of the precast panels. A conceptual wall system would consist of metal panel with steel girts, air space, rigid insulation, air barrier membrane similar to what was utilized in the pool.

Estimated Cost: \$450,000

Priority: Long Term, recommended within 5 to 10 years.


- .4 The concrete masonry block walls, comprising the northeast portions of the building containing dressing rooms, men's and women's washroom, corridors, etc., are exhibiting signs of badly deteriorated masonry block. Deterioration includes cracking of block faces, delaminated mortar joints, spalling paint, indicative of potential air leakage through the masonry wall assembly.

Photograph 3.3.1.4-1: Degraded block wall.






Photograph 3.3.1.4-2: Side view of the transition from the concrete panel wall to the concrete block wall. Note thermal anomaly at the intersection of the two wall assemblies, possibly caused by air leakage. Additional investigation is required (Refer to Recommendation 3.3.1.3-1).



Photograph 3.3.1.4-3: View of the concrete block wall at the North East corner. Note the brighter spots are mechanical system vents evenly spaced below the parapet level. A thermal anomaly is present along the assumed roof line.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

The wood trim on exterior face of the women's change room, below the cap flashing, is badly weathered and cracking (Photograph 3.3.1.4-4).

Photograph 3.3.1.4-4: Degraded block wall and weathered wood trim.



Water damaged gypsum wall board was observed in the north corridor on the north wall perpendicular to the east exterior block wall (Photograph 3.3.1.4-5). Paint was peeling from the interior surface of the east exterior block wall, adjacent the exit door (Photograph 3.3.1.4-6) was also visible. The conditions are indicative of moisture infiltration or condensation on this surface.

Photograph 3.3.1.4-5: Water damaged gypsum wall board.





Photograph 3.3.1.4-6: Paint peeling from concrete block.



Recommendation 3.3.1.4-1: Remove and wood trim on exterior face of the women's change room, below the cap flashing.

Estimated Cost: \$5,000

Priority: Long Term Considerations/Recommended Improvements (not time critical)

Recommendation 3.3.1.4-2: The exterior concrete block walls are in fair to poor condition. Repairs are required in the short term to address deterioration of the mortar joints and masonry control joints.

Estimated Cost: \$25,000

Priority: Short Term, recommended within 1 year.

Recommendation 3.3.1.4-3: Remove and replace masonry face block including insulation and vapour permeable air barrier membrane at the north east portions of the building containing dressing rooms, men's and women's washroom, corridors, etc. Localized repairs of masonry back-up and joint repointing.

Estimated Cost: \$100,000

Priority: Medium Term, recommended within 1 to 5 years.

- .5 Water staining was observed in the interior of the main entrance, along the east wall, indicating potential roof leakage at this interface. Refer to Section 3.3.3 for roofing recommendations.



Photograph 3.3.1.5-1: Water staining at main entrance.



- .6 Water staining was observed on the ceiling in the main entrance foyer, specifically at light fixture locations, and along the east wall between the foyer and the auditorium, indicating potential roof leakage. Refer to Section 3.3.3 for roofing recommendations.

Photograph 3.3.1.6-1: Water staining on ceiling at light fixture locations.





Photograph 3.3.1.6-2: Water staining on ceiling along the east wall.



- .7 Moisture staining and evidence of leakage was observed within the corridor adjacent to the east exit door (Photograph 3.2.2.1-1) and below the transition from the low roof over main hall to the stairwell (Photograph 3.2.2.1-2). Refer also to Section 3.3.3 for recommendations.

Photograph 3.2.2.1-1: Evidence of leak in ceiling tile at east exit door.





Photograph 3.2.2.1-2: Evidence of leakage along the transition from the low roof over the hall to the stairwell.



- .8 Water staining was observed on the ceiling tiles in the corridor leading to the coat room at the stairwell corner, as well as within the coat room along the west wall, indicating potential roof leakage at this interface. Refer also to Section 3.3.3 for recommendations.

Photograph 3.3.1.8-1: Water staining on ceiling tiles.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .9 Water staining was observed on the auditorium ceiling, specifically at joist to deck locations, indicating potential roof leak. Refer also to Section 3.3.3 for recommendations.

Photograph 3.3.1.11-1: Water staining at joist to deck locations.



- .10 Paint was peeling from the underside of the roof deck in the daycare, specifically along the south wall, indicating potential moisture issues along this interface.

Photograph 3.3.1.12-1: Paint peeling from steel deck.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .11 Water staining was observed on the interior face of the south block wall in the daycare, indicating potential water infiltration or condensation. Further investigation is warranted. Refer to Recommendation 3.3.1.3-1.

Photograph 3.3.1.13-1: Water staining on concrete block.



3.3.2 Glazing

- .1 The windows along the south elevation, servicing the auditorium, were observed to be aluminum framed interior glazed ribbon windows consisting of dual pane, 6 mm interior and exterior lite, clear glass, sealed units with 12 mm PVC spacers. All windows of this type are fixed and have no operable components.

All sealed units of this type exhibited evidence of seal failure including fogging, condensation, streaking, and accumulation of desiccant residue on interior surfaces of lites. Condensation on the metal panels above and below the window unit is indicative of a potential heat loss location and furthermore potential moisture accumulation with the wall assembly. Interior staining and streaking of adjacent surfaces and tile below the window were also observed. No visible date stamps were observed.

No visible cracks were observed in any of the sealed units. Generally, the exterior gaskets were intact and not overly degraded due to environmental exposure.



Photograph 3.3.2.1-1: Typical example of visual evidence of seal failure, including condensation and accumulation of desiccant residue on the interior surfaces of lites in the. Due to the rain, this is difficult to see in this photograph; however, the cloudiness is indicative of seal failure.



Recommendation 3.3.2.1-1: Existing aluminum ribbon windows along the south elevation are exhibiting sealed unit failure. Short term replacement is recommended to increase thermal performance, visibility, and occupant comfort. It is recommended that associated flashing and sealant replacement and repairs be conducted simultaneously to increase the performance and durability of the window tie into the overall envelope system.

Estimated Cost: \$7,500

Priority: Medium Term, recommended within 1 to 5 years.

3.3.3 Roof

- .1 The roof assemblies on the Recreation Centre and adjacent roof facets are consistent with a typical 4-ply built up roof (Photograph 3.3.3.1-1). The existing roof assemblies are similar in construction and condition. All roof facets have splits and cracks, and evidence of deterioration that indicates that it has reached the end of its useful life. Evidence of repairs was also observed presumably to address water infiltrating into the recreation centre (Photograph 3.3.3.1-2). The lack of insulation had adversely affected the existing membrane due to heat rise through the assembly. Replacement of the roof is recommended in the short term.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 3.3.3.1-1: Partial view of Recreation Centre roof R10 looking west to R9. Existing repairs visible.



Photograph 3.3.3.1-2: View blister and membrane splits on Roof R8.



Recommendation 3.3.3.1-1: Replace existing roofs R7, R8, and R10.

Estimated Cost: 280,000.00

Priority: Short Term recommended one year.



4. Indoor Swimming Pool (PI-05)

At the request of the City of Winnipeg Planning Property & Development Department, a structural, building envelope, and mechanical systems assessment of the St. James Civic Centre Pool was completed by Crosier Kilgour & Partners and Epp Siepman personnel in late 2018 and early 2019. The purpose of the investigation was to provide an opinion as to the current condition of the structure, cladding, windows and roofing, identify areas of distress, and provide recommendations aimed at extending the service life of the structure and building envelope components.

The following sections provide a summary of the findings presented in the Crosier Kilgour & Partners reported dated April 4, 2019.

4.1 Exterior

4.1.1 Pavement, Sidewalks, Structures

- .1 The asphalt paving along the west elevation is in poor condition with significant crack and deterioration.

Photograph 4.1.1.1-1: Partial view of west elevation pavement.



Recommendation 4.1.1.1-1: Complete localized repairs to existing sidewalks and curbs to address potential tripping hazards and deterioration. Repairs will range from localized patches to full depth replacement.

Estimated Cost: \$15,000

Priority: Short Term, recommended within 1 year.

Recommendation 4.1.1.1-2: Repave existing driveway along the west elevation with new asphalt topping.

Estimated Cost: \$60,000

Priority: Medium Term, recommended within 1 to 5 years.



- .2 Damage to the concrete joint at the west exit door was observed.

Photograph 4.1.1.2-1: Partial view of entrance landing/pavement joint.



Recommendation 4.1.1.2-1: Complete localized repairs to address concrete deterioration and tripping hazard at transition.

Estimated Cost: \$3,000

Priority: Short Term, recommended within 1 year.

4.1.2 Grading

- .1 The asphalt pavement on west side is typically well sloped away from building.
- .2 Landscaping on the south and west elevations are finished consists of sod. The grade appears to slope back towards building slightly within about 5 feet.

Photograph 4.1.2.2-1: Partial view of south elevation grading.





Recommendation 4.1.2.2-1: Re-grade existing sod and soil to direct water away from the building.

Estimated Cost: \$5,000

Priority: Short Term, recommended within 1 year.

4.2 Structural

4.2.1 Basement/Crawlspace

- .1 A crawlspace is located below the pool deck and tanks. No evidence of a vapour retarder was observed on the crawlspace floor (Photograph 4.2.1.1-1). The exposed soil within the crawlspace appeared to be dry. Refer also to 4.2.1.1.

Photograph 4.2.1.1-1: Partial view of boardwalk along east side of crawlspace. No ground cover is present below pool tanks or boardwalks.



Photograph 4.2.1.1-2: Unfinished crawlspace floor show exposed soil.



Recommendation 4.2.1.1-1: The crawlspace does not have a functioning vapour barrier. Remediation of the crawlspace is recommended including grading of the existing soil to direct water away from structural members, installation of a new drainage system and



sump pits (if required, see mechanical), and installation of a vapour retarder and sand cover. Installation of new sub-surface drainage, vapour barrier, and sand cover is recommended within 5 years. Refer to Recommendation 3.2.1.1-1.

Estimated Cost: Costs included in Recommendation 3.2.1.1-1

Priority: Long Term, recommended within 5 to 10 years.

- .2 The basement floor slab in boiler room was painted in 2018. Localized evidence of concrete scaling was observed around a sump pit. The scaling has been painted over indicating that it was present prior to 2018. Notwithstanding localized surface defects, the slab is in good overall condition.

Photograph 4.2.1.2-1: Partial view of basement slab scaling.



Recommendation 4.2.1.2-1: Complete localized repairs to slab to address miscellaneous surface defects.

Estimated Cost: \$5,000

Priority: Recommended Improvements (not time critical)

- .3 The floor slab within the Boiler Room is not painted. Some cracking and spalling was observed along with a large crack was observed at west end of slab (Photograph 4.2.1.3-1).



Photograph 4.2.1.3-1: Partial view of basement slab scaling.



Recommendation 4.2.1.3-1: Complete localized repairs to slab to address miscellaneous surface defects.

Estimated Cost: \$3,000

Priority: Recommended Improvements (not time critical)

- .4 Localized spalling of the Air Handler Room floor slab was observed around a floor drain (Photograph 4.2.1.4-1)

Photograph 4.2.1.4-1: Spall at floor slab.



Recommendation 4.2.1.4-1: Complete localized repairs to slab to address miscellaneous surface defects.

Estimated Cost: \$3,000

Priority: Recommended Improvements (not time critical)



4.2.2 Swimming Pool and Pool Deck

- .1 Delamination of the underside of the concrete pool deck was observed at several locations from within the basement and crawlspace. Photographs 4.2.2.1-1 and 4.2.2.1-2 show typical delamination of the slab soffit. The delamination is a result of corrosion of the embedded reinforcing steel. Efflorescence is also visible which is caused by water seepage through cracks in the concrete.

Photograph 4.2.2.1-1: Soffit delamination and spalling at pool tank drain.



Efflorescence and corrosion staining were observed along the existing construction joints in the pool walls and soffit (Photograph to 4.2.2.1-2). The conditions are caused by water seepage through the joint.

Photograph 4.2.2.1-2: Typical concrete deterioration.



It was reported by on-site personnel that concrete repairs have been completed by City personnel to address deterioration of the pool deck slab (Photograph 4.2.2.1-3). Repairs consisted of chipping out loose concrete patching with a concrete repair material. Further repairs are required around opening in the main floor slab.



Photograph 4.2.2.1-3: Concrete repairs and deterioration around opening in the main floor slab.



Overall, the deterioration of the concrete is directly related to water seepage through the concrete pool walls. It also indicates that the existing tile is not providing an effective waterproof barrier.

Recommendation 4.2.2.1-1: Structural concrete repairs are required to address existing deterioration. Given the extent of leakage and the fact that the pool water contains chlorine which enhances corrosion, the likelihood of a rapid increase in corrosion and delamination is very high. Repairs are therefore required in the short term to address existing deterioration. Repairs will include removal of all loose concrete down to a sound substrate, exposing all corroding reinforcing steel, sandblasting existing concrete and reinforcing steel, and infilling with a proprietary concrete repair material.

For the purposes of budgeting, it is assumed that 2% of the surface area of the pool deck and tank soffit will require repair. Additional investigation beyond the scope of this report is required to identify and quantify repair areas.

Estimated Cost: \$80,000

Priority: Short Term, recommended within 1 year.

Recommendation 4.2.2.1-2: A structural assessment of the pool deck and tank is recommended to identify and quantify existing repair areas.

Estimated Cost: \$10,000

Priority: Short Term, recommended within 1 year.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .2 A visual inspection with localized chain drag soundings was completed on the top surface of the pool decks. Localized areas of debonding of the tile was observed within the pool tanks.

Recommendation 4.2.2.2-1: Water seepage through the pool slabs and walls indicating that the existing tile is not providing an effective waterproof barrier. In order to address the root cause of the concrete deterioration and extend the service life of the repairs, it is recommended that the existing tile be removed and replaced with a new pool lining and tile finish.

Estimated Cost: \$275,000

Priority: Medium Term, recommended within 1 to 5 years.

Recommendation 4.2.2.2-2: As an interim measure, injection of the cracks using a hydrophobic urethane resin can be completed to allow repairs to be deferred.


Estimated Cost: \$15,000

Priority: Short Term, recommended within 1 year.

4.2.3 Main Floor Structure and Common Areas


- .1 The mezzanine guardrail in the gym is approximately 89 cm (35") high and does not have vertical pickets. The guardrail as constructed does not meet current building code requirements with respect to height, climability, and design. Upgrading to meet current codes is not necessarily required but would depend on when the gym was first occupied. Notwithstanding, the conditions represent a potential safety hazard and upgrading the guardrail is recommended.

Photograph 4.2.3.1-1: Gym mezzanine showing existing guardrail.





Photograph 4.2.3.1-2: Gym mezzanine guardrail height.



Recommendation 4.2.3.1-1: Upgrade existing guardrail to meet current code requirements.

Estimated Cost: \$10,000

Priority: Required Repairs (within 3 months)

- .2 Cracking in the entrance floor slab was observed (Photograph 4.2.3.2-1). The cracking appears to be old.

Photograph 4.2.3.2-1: Cracking in main floor slab.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Recommendation 4.2.3.2-1: Complete localized repairs to slab to address cracking and miscellaneous surface defects. Repairs may consist of routing out cracks and infilling with a semi-rigid joint filler

Estimated Cost: N/A – Non-capital expense

Priority: Maintenance

4.2.4 Building Superstructure

- .1 The steel roof joists and metal roof deck in the storage room at the northwest corner of the pool has minor to moderate surface corrosion visible (Photograph 4.2.4.1-1). Similar conditions were observed within the pool storage room at the west end of the building.

Photograph 4.2.4.1-1: Partial view of roof framing. Step cracking in northwest corner also visible (yellow arrow).



The roof joists are exposed and visible within the change rooms. On-site personnel indicated that the joists and deck were painted approximately 3 years ago with an epoxy-based paint. The joists are generally in good condition however some rust staining showing through.

Photograph 4.2.4.1-2: Partial view of roof framing.





Photograph 4.2.4.1-3: Partial view of roof framing.



Recommendation 4.2.4.1-1: Minor surface corrosion was visible on structural framing. Removal or corrosion and repainting will be required periodically throughout the life of the structure. Consideration should be given to the environmental conditions which selecting materials. Painting is considered normal maintenance.

Estimated Cost: N/A – Non-capital expense

Priority: Maintenance.

- .2 The roof over entrance and pool consists of precast double tees. Evidence of leakage was observed on the roof joists over the pool (Photograph 4.2.4.2-1). On-site personnel indicated that the leakage stains are old and have been repaired approximately 2 years ago. No leakage is presently occurring, and no work is required.

Photograph 4.2.4.2-1: Partial view of roof framing over pool showing evidence of past leakage.



- .3 The gym at the northwest corner is constructed of a pre-engineered steel frame building. The structural framing is in good condition. An active roof leak above gym was observed during the site visit. Refer to Section 3.3.4 for roofing recommendations.



Photograph 4.2.4.4-1: Partial view of roof framing over pool showing evidence of past leakage.



- .4 Leakage reported above corridor. Leakage is reported in the spring. Leakage during summer months was not reported.

4.2.5 Roof (Exterior)

- .1 Access to the roof is provided by way of fixed access ladders on the west elevation. The access ladder does not have a ladder cage but is less than 4 metres in height and therefore does not require one. The access ladders are in reasonable overall condition. Minor surface corrosion was visible.


Recommendation 4.2.5.1-1: Periodic repainting will be required to address corrosion. Painting is considered normal maintenance.

Estimated Cost: N/A – Non-capital expense

Priority: Maintenance.

- .2 The access ladder from west roof to South roof is loose and needs repair. Similar conditions were observed at the ladder from the east roof.

Photograph 4.2.5.2-1: Access ladder from the west roof to south roof.





Recommendation 4.2.5.2-1: Repair loose connection at low access ladders to south roof.

Estimated Cost: \$5,000

Priority: Required Repairs (within 3 months)

- .3 The existing concrete entrance canopy over the south entrance is in good condition. Localized hammer soundings were completed and did not reveal any evidence of delamination or deterioration of the concrete

4.3 Building Envelope

4.3.1 Walls and Cladding

- .1 At the main entrance canopy along the South elevation, thermal anomalies were observed at numerous locations especially at the top of the existing precast concrete band and at the column support for the canopy.
- .2 Along the West elevation, residual moisture/condensation was evident at the exterior face of the existing metal cladding. Thermographic scan in Appendix B confirmed air leakage and thermal bridging at the horizontal support of the existing metal panel. Vehicular damage noted at the bottom section of the metal cladding including base flashing.
- .3 Badly deteriorated masonry block units including mortar joints were observed along the West elevation at the exterior of the women's locker/washroom due to air leakage at the masonry wall assembly.

Photograph 4.3.1.3-1: Over-all view of the main entrance at the St. James Civic Centre.





Photograph 4.3.1.3-2: View of thermal bridging at top of vertical concrete bands and along column supporting the entrance canopy, between the entrance and the open air above.




Photograph 4.3.1.3-3: Condensation observed at the existing metal cladding along the West elevation.





Photograph 4.3.1.3-4: Thermal anomalies evident along the horizontal support of the metal cladding corresponding to the location on condensation shown at Photograph above.




Photograph 4.3.1.3-5: Moisture stains at the existing masonry face block with localized block unit and mortar joint deterioration outside the women's locker/washroom.






Photograph 4.3.1.3-6: West elevation at masonry wall and metal cladding transition.




Photograph 4.3.1.3-7: Close up of vertical transition at masonry wall and metal cladding. Clearer view of thermal bridging on masonry is visible.





Photograph 4.3.1.3-8: Pool room window with thermal bridging at cladding fasteners and cladding above and below the window unit.



Recommendation 4.3.1.3-1: Remove and replace masonry face block including insulation and vapour permeable air barrier membrane at the exterior of the women's locker/washroom area. Localized repairs of masonry back-up and joint repointing.

Estimated Cost: \$45,000

Priority: Medium Term, recommended within 1 to 5 years.

Recommendation 4.3.1.3-2: Remove and replace metal cladding including through-wall flashing, insulation and air barrier membrane.

Estimated Cost: \$350,000

Priority: Long Term Considerations/Recommended Improvements (not time critical)

4.3.2 Glazing

- .1 The windows along the west end of the south elevation, servicing the pool area, were observed to aluminum framed interior glazed ribbon windows consisting of dual pane, 6mm interior and exterior lite, clear glass, sealed units with 12mm PVC spacers. All windows of this type are fixed and have no operable components.

All sealed units of this type exhibited evidence of seal failure including fogging, condensation, streaking, and accumulation of desiccant residue on interior surfaces of lites. Condensation on the metal panels above and below the window unit is indicative of a potential heat loss location and furthermore potential moisture accumulation with the



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

wall assembly. Interior staining and streaking of adjacent surfaces and tile below the window was also observed. No visible date stamps were observed.

No visible cracks were observed in any of the sealed units. Generally, the exterior gaskets were intact and not overly degraded due to environmental exposure.

Photograph 4.3.2.1-1: Typical example of visual evidence of seal failure, including condensation and accumulation of desiccant residue on the interior surfaces of lites in the south elevation pool area windows.




Photograph 4.3.2.1-2: Condensation on the metal panels above the south elevation pool windows.





Photograph 4.3.2.1-3: Interior staining and streaking of adjacent surfaces and tile below the south elevation pool windows.



Recommendation 4.3.2.1-1: Existing aluminum ribbon windows along the west end of the south elevation are exhibiting sealed unit failure. Short term replacement is recommended to increase thermal performance, visibility, and occupant comfort. It is recommended that associated flashing and sealant replacement and repairs be conducted simultaneously to increase the performance and durability of the window tie in to the overall envelope system.

Estimated Cost: \$7,500 (double if east side of south elevation is included)

Priority: Medium Term, recommended within 1 to 5 years.

- .2 There are 10 second storey windows on the south elevation. The center 6 windows are single paned operable aluminum vertical hung sliders within aluminum frames complete with exterior insect screens. Insect screens were missing from 2 of the 6 units. The units appear to have been installed backwards, with the operation levers and locking pins to the exterior. A second vertical hung slider window was installed on the building interior. No visible date stamps were observed.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 4.3.2.2-1: Partial view of second story windows showing center single paned operable aluminum vertical hung sliders within aluminum frames.



Condensation accumulation was visible on the interior surface of the glass.

Photograph 4.3.2.2-2: Typical example of condensation accumulation on interior surface of the glass.



No visible cracks were observed in any of the vertical slider units. There was no sealant installed at aluminum head, sill, and jamb flashing, or around window frame perimeter to flashing interfaces, creating opportunity for bulk water infiltration.



Photograph 4.3.2.2-3: Typical window sill showing lack of sealant at flashing interfaces.



Recommendation 4.3.2.2-1: Existing operable aluminum vertical hung slider windows along the upper storey of the south elevation are not energy efficient or high-performance units. Short term replacement is recommended to increase thermal performance, visibility, and occupant comfort. It is recommended that associated flashing and sealant replacement and repairs be conducted simultaneously to increase the performance and durability of the window tie into the overall envelope system.

Estimated Cost: \$6,000

Priority: Medium Term, recommended within 1 to 5 years.

- .3 There are 10 second storey windows on the south elevation. Four window units, 2 at each end, appear to be retrofit installations as evidenced by the dissimilar metal cladding infill below, comprising of aluminum framed interior glazed ribbon windows consisting of dual pane 5mm interior and exterior lite, clear glass, sealed units with 15mm metal spacers. These windows are fixed and have no operable components. The sealed glazing units are dated 1999, 20 years old, and as such are nearing their expected service life of 25 years.

The sealed units did not exhibit visible evidence of seal failure, frost point testing of two of the four window units indicated intact seals.

No visible cracks were observed in any of the sealed units. The exterior glazing sealant was severely degraded due to environmental exposure, including cracking and stiffening of the sealant. Mildew was observed on the sealant and adjacent aluminum frame along the head and upper portion of the jambs.



Photograph 4.3.2.3-1: Typical second story aluminum framed window.



Sealant at flashing interfaces is degraded due to environmental exposure, including cracking and stiffening of the sealant, creating opportunity for bulk water infiltration.

Photograph 4.3.2.3-2: Typical example of degraded glazing sealant.



Photograph 4.3.2.3-3: Typical example of degraded glazing sealant and mildew growth at head and upper portion of the jambs.



Photograph 4.3.2.3-4: Typical example of degraded sealant at flashing interfaces.



Recommendation 4.3.2.3-1: Existing aluminum framed interior glazed ribbon windows along the upper storey of the south elevation are nearing their expected service life of 25 years. Short term replacement is recommended to increase thermal performance, visibility, and occupant comfort. It is recommended that associated flashing and sealant replacement and repairs be conducted simultaneously to increase the performance and durability of the window tie in to the overall envelope system.

Estimated Cost: \$4,000

Priority: Medium Term, recommended within 1 to 5 years.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .4 The south elevation entrance consists of 3 sets of glazed aluminum doors, 2 push and 1 slider, complete with curtain wall framed exterior glazed sidelights and transoms. Both door and window glazing consist of dual pane 6mm interior and exterior lite, clear glass, sealed units with 12mm PVC spacers. All windows are fixed and have no operable components. Doors bear Kawneer manufacturer label. The sealed glazing units are not dated.

Photograph 4.3.2.4-1: South elevation entrance consisting of three sets of glazed aluminum doors, 8 curtain wall framed sidelight windows, and 5 transom windows.



Though the sealed units did not exhibit visible evidence of seal failure, though frost point testing of three of the 11 window units revealed seal failure in each instance. Significant water staining was observed on the interior aluminum frames and adjacent surfaces, indicating areas potentially prone to condensation.

Photograph 4.3.2.4-2: Water staining on aluminum frames and adjacent surfaces.






Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

No visible cracks were observed in any of the sealed units. Being situated below the entrance canopy and somewhat protected from the elements, the exterior gaskets of these units were minimally degraded, with the upper portions and heads exhibiting signs of chalking and stiffening due to accumulation of residue.

Photograph 4.3.2.4-3: Typical example degraded gasket showing chalking and residue accumulation.



Sealant applied to the exterior frame to wall interfaces was deteriorated and separating from the wall surface, creating opportunity for bulk water infiltration. Similar conditions were observed on the interior surfaces.

Photograph 4.3.2.4-4: Typical example of degraded sealant at frame to wall interface.





Recommendation 4.3.2.4-1: Existing glazed aluminum doors and associated curtain wall framed entrance windows are exhibiting sealed unit failure. Short term replacement is recommended to increase thermal performance, visibility, and occupant comfort. It is recommended that associated flashing and sealant replacement and repairs be conducted simultaneously to increase the performance and durability of the window tie in to the overall envelope system.

Estimated Cost: \$20,000

Priority: Medium Term, recommended within 1 to 5 years.

4.3.3 Roofing

- .1 Overall, our observations of the existing main pool, vestibule, and upper adjacent roof systems the condition is good and is performing as intended. Photograph 4.3.3.1-1 Drainage on the pool roof is satisfactory and sloped adequately to the vestibule roofs interior drains. The assembly installed on all the main roof comprises of SBS base and granulated cap membrane, support panel over rigid insulation, air vapor barrier membrane, and gypsum exterior grade support panel on existing deck. The SBS 2-ply flashing membranes, and pre-finished metal flashing are in good condition. Photograph 4.3.3.1-2.

Recommendation 4.3.3.1-1: Annual maintenance required.

Estimated Cost: N/A – Non-capital expense

Priority: Maintenance

Photograph 4.3.3.1-1: Showing Main roof over pool R9.





Photograph 4.3.3.1-2: View of upper roof facet R6.



- .2 The low roof R5 (Photograph 4.3.3.2-1) and canopy roof R12 (Photograph 4.3.3.2-2) are in poor condition. Drainage on the pool roof R9 is satisfactory to the interior drains. Currently the roof shows exposed membrane throughout and areas of ponding water. We observed multiple repairs on the existing curbs and roof penetrations (Photograph 4.3.3.2-3). The existing roof system is a typical 4-ply asphaltic membrane, fiber support panel, expanded polystyrene insulation, organic felt vapor barrier on a gypsum support panel.

The canopy system is similar to the low roof R5, however non-insulated. The existing assembly is original to this roof facet and has outlived its service life. Due to the age of the membrane further splits and cracks may develop which will allow water to infiltrate into the assembly and building causing interior damages. The lack of insulation had assisted the current system to remain adequate, due to the heat rise through the assembly and slowing the overall aging process of the asphaltic membrane. The overall condition of the asphaltic membrane is brittle due to the age and we recommend replacement on these roof facets.

Recommendation 4.3.3.2-1: Replace existing roofs R5 and R12.

Estimated Cost: \$120,000

Priority: Short Term, recommended within 1 year.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Photograph 4.3.3.2-1: Showing lower roof R5.



Photograph 4.3.3.2-2: View of canopy roof R12.





Photograph 4.3.3.2-3: View of existing repairs.



- .3 The metal roof systems R3 and R4 (Photograph 4.3.3.3-1) are in poor condition. The existing roof system is a typical metal standing seam roof panel, with underlying blanket insulation. The existing assembly is original to this roof facet and is near the end of its service life. We observed several repairs, randomly throughout the metal panels. Due to the age of the galvanized panels and minor defects, further repair will be necessary to extend the roof system life cycle. We observed openings at the roof penetrations and roof wall interface that has allowed water to infiltrate into the building.

Recommendation 4.3.3.3-1: Roof maintenance is required on metal roofs R3 and R4.

Estimated Cost: \$10,000

Priority: Short, recommended within 1 year.

Photograph 4.3.3.3-1: View of Gym Roof R4.





Photograph 4.3.3.3-2: Showing repair at roof wall interface.



4.4 Mechanical

4.4.1 HVAC

- .1 AHU-2 was not designed for use in pool environment and the mechanical cooling compressors have failed. The supply fan motor and mounting have also sustained considerably corrosion.

Photograph 4.4.1.1-1: Corroded supports for fan motor





Photograph 4.4.1.1-2: Failed Compressors in AHU-2



Currently warm humid pool air is returned to AHU-2, located on the roof, where it is mixed with preheated fresh air before being reintroduced back to AHU-1 located in the basement. With the failure of the mechanical cooling, there is no longer any provision for mechanical cooling. Conditioning relies on exhaust from the change rooms and introduction of equivalent fresh air to control humidity levels. No dedicated exhaust or relief for pool deck area and no controlled system is in place to reduce or relieve humidity from pool deck leads to:

- Elevated humidity levels within the pool deck area due to reduced ability to dehumidify;
- Humid air migrating to other areas adjacent to the pool due to uncontrolled balance of exhaust and fresh air;
- Moisture condensing on various surfaces where the surface temperature is below the dew point of the interior air, i.e. AHU-1 intake ductwork within pool supply storage room is discoloured and pitted as a result of condensation. AHU-1 is original equipment and is recommended to be replaced.

Photograph 4.4.1.1-3: Discoloured, corroded and pitted ductwork exposed in pool supply/storage room.





Recommendation 4.4.1.1-1: It is recommended that exhaust air removed from and fresh air introduced to the pool area be dealt with deliberately with a dedicated outdoor air system (DOAS) complete with exhaust fan, supply fan and some form of heat recovery. The intent is to provide control over:

- Humidity levels in the pool deck area and;
- Relative space static pressure between the pool deck area and surrounding adjacent spaces and outdoors.

The above objectives can be met by removing AHU-2 and associated ductwork and electric heat. AHU-2 should be replaced with a DOAS unit with heat recovery to provide balanced exhaust and fresh supply air to the pool deck air via AHU-1. AHU-1 shall remain in place to provide space conditioning as is the current operation. New DOAS unit shall be suitable for use in high humidity and corrosive pool environments. It shall also be sized to meet current code requirements for ventilation and exhaust air. The air streams shall be balanced to maintain slight negative pressure to alleviate migration of humidity to other adjacent areas of the building. Inclusion of mechanical cooling is recommended to provide ability to further control pool deck humidity.

Estimated Cost: \$130,000

Priority: Short Term, recommended within 1 year.

Recommendation 4.4.1.1-2: Replacement and insulation of the exposed AHU-1 intake ductwork within the pool supply/storage room is recommended to eliminate the condensation forming on the intake ductwork.

Estimated Cost: \$7,500

Priority: Short Term, recommended within 1 year.

- .2 Air Handling Unit AHU-1 is past its published service life and though continues to operate there is elevated risk in maintaining this unit as it continues to age. Additionally, internal components have been subjected to a high humidity and corrosive environment for the duration of its service life which could contribute to sudden failure

Recommendation 4.4.1.2-1: It is recommended that AHU-1 be replaced with new system selected to meet current code requirements for ventilation and supply air for pool applications.

Estimated Cost: \$50,000

Priority: Long Term, recommended within 5 to 10 years.



- .3 The HVAC and domestic boilers are original equipment and past their published service life. There is system redundancy and they appear to be functioning reliably but going forward there is elevated risk in maintaining the existing boilers as they continue to age.

Recommendation 4.4.1.3-1: It is recommended that the boilers be replaced along with the various HVAC pumps within the boiler room to provide increased control over operation and increased operational efficiency

Estimated Cost: \$120,000

Priority: Medium Term, recommended within 1 to 5 years.

- .4 The Boiler Room unit on the roof, AHU-3, is nearing the end of its published service life but shall remain in place while the existing boilers are in place as it provides conditioning for the boiler room due to the required volume of combustion air necessary for the operation of the boilers.

Recommendation 4.4.1.4-1: Upon replacement of the boilers, AHU-3 and its function should be re-evaluated to determine whether it is still required to condition the boiler room following redesign of the combustion air to accommodate new boilers.

Estimated Cost for demolition: \$15,000

Priority: Medium Term, within 1 to 5 years

- .5 Pneumatic controls are operational but past their published service life. Some control and monitoring are currently provided by a central Johnson Controls system.

Recommendation 4.4.1.5-1: It is recommended that the existing pneumatic controls be replaced with current digital controls to provide increased monitoring and control capability for the facility.

Estimated Cost: \$110,000

Priority: Long Term Considerations/Recommended Improvements (not time critical)

- .6 Existing change room exhaust fans are original equipment and have been operating in a high humidity corrosive environment.

Recommendation 4.4.1.6-1: It is recommended that the exhaust fans be reviewed for damage or effects due to operating in a humid and corrosive environment. They shall be balanced to maintain exhaust air volumes required by current code and for operation in conjunction with the pool supply and exhaust systems.

Estimated Cost: \$9,000

Priority: Long Term Considerations/Recommended Improvements (not time critical)



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .7 The existing weight room unit, AHU-4 is nearing the end of its service life but is still functional.

Recommendation 4.4.1.7-1: It is recommended that this unit remain in place until its published service life is reached.

Estimated Cost: \$9,000

Priority: Long Term Considerations/Recommended Improvements (not time critical)

- .8 If structural resolves that sump pit(s)/pump(s) are required to serve additional or remediated weeping tile systems in the crawl space (Recommendation 3.2.1.1-1), a duplex sump pump is recommended per required location.

Recommendation 4.4.1.8-1: Crawlspace sump pits.

Estimated Cost: \$12,000*

*Note that cost is subject to some variability based on required length of discharge piping.

Priority: Long Term, recommended within 5 to 10 years.



5. Arena (AR-03)

At the request of the City of Winnipeg Planning Property & Development Department, a structural and building envelope assessment of the St. James Civic Centre Arena, was completed by Crosier Kilgour & Partners personnel in early 2018. The purpose of the investigation was to provide an opinion as to the current condition of the structure, cladding, windows and roofing, identify areas of distress, and provide recommendations aimed at extending the service life of the structure and building envelope components.

The following sections provide a summary of the findings presented in the Crosier Kilgour & Partners reported dated October 2018.

5.1 Exterior

5.1.1 Pavement, Sidewalks, Structures

- .1 The exterior concrete slabs and pavements vary in condition (Photograph 5.1.1.1-1). Localized maintenance repairs are required.

Photograph 5.1.1.1-1: Deterioration of exterior concrete.



Recommendation 5.1.1.1-1: Complete localized concrete repairs.

Estimated Cost: \$5,000

Priority: Short Term, recommended within 1 year.

5.2 Structural

5.2.1 Basement/Crawlspace

- .1 A crawlspace is located below the arena ice surface. Access to the crawlspace is provided by way of an access hatch in the north wall of the electrical room. The condition of the



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

crawlspace and main floor slab represents a significant concern. At the time of the site visit, standing water was visible within the majority of the crawlspace (Photograph 5.2.1.1-1 and 5.2.1.1-2) and no evidence of vapour retarder was observed. Drainage lines and a sump pit was observed along the west side of the crawlspace. The standing water is contributing to high humidity levels and corrosion of metal hangers and conduits (Photograph 5.2.1.1-3), and delamination of the rink slab soffit (Photographs 5.2.1.1-1, 5.2.1.2-1, 5.2.1.2-2).

Note: A cursory review of the crawlspace was completed during the review of the Recreation Centre (RC-22). The crawlspace exhibit significantly less standing water. Sweating of the slab soffit was still visible.

Photograph 5.2.1.1-1: Partial view of crawlspace showing standing water. Sweating of the slab soffit and delamination also visible.



Photograph 5.2.1.1-2: Standing water adjacent to column.





Photograph 5.2.1.1-3: Corrosion of conduits and hangers.



Recommendation 5.2.1.1-1: The arena crawlspace is in poor condition. Water infiltration into the crawlspace is causing deterioration of the main floor slab, and mechanical/electrical services. Based on the level of deterioration, a comprehensive remediation of the crawlspace is required to address structural deterioration and water infiltration into the crawlspace. A conceptual remediation would include structural concrete repairs (Refer to Recommendation 5.2.1.2-1) to address delamination of the slab soffit, grading of the existing soil to direct water away from structural members, installation of a new drainage system and sump pits, installation of a vapour retarder and sand cover, and improvements to exterior grading. Repair of mechanical and electrical services, and improvements to the ventilation system will also be required. Further investigation by a mechanical engineer would be required. Repairs are recommended in 2019.

Estimated Cost: \$670,000

Priority: Short Term, recommended within 1 years.

Recommendation 5.2.1.1-2: Investigation by a mechanical engineer would be required. Repairs are recommended in 2019.

Estimated Cost: \$10,000

Priority: Short Term, recommended within 1 years.

- .2 Delamination of the underside of the arena rink slab was observed at numerous locations from within the crawlspace. Photographs 5.2.1.2-1 and 5.2.1.2-2 show typical delamination of the slab soffit. The delamination is a result of corrosion of the embedded reinforcing steel. Efflorescence is also visible which is caused by water seepage through cracks in the concrete.



Photograph 5.2.1.2-1: Typical slab soffit delamination.



Photograph 5.2.1.2-2: Typical slab soffit delamination.



Recommendation 5.2.1.2-1: Complete structural concrete repairs. Structural concrete repairs are required to address existing deterioration. Repairs are required in the short term to address existing deterioration. Repairs will include removal of all loose concrete down to a sound substrate, exposing all corroding reinforcing steel, sandblasting existing concrete and reinforcing steel, and infilling with a proprietary concrete repair material.

For the purposes of budgeting, it is assumed that 10% of the surface area of the arena slab will require repair. Additional investigation beyond the scope of this report is required to identify and quantify repair areas.

Estimated Cost: \$380,000

Priority: Short Term, recommended within 1 year.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Recommendation 5.2.1.2-2: A structural assessment of the arena rink slab is recommended to identify and quantify existing repair areas.

Estimated Cost: \$15,000

Priority: Short Term, recommended within 1 year.

- .3 The exterior concrete block walls are in fair to poor condition (Photographs 5.2.1.3-1, 5.2.1.3-2, Photograph 5.2.1.3-3). Localized deterioration of the concrete block walls and mortar joints was observed. The exterior masonry control joints are in poor condition and have exceeded their useful life. The structural steel lintels over the doors are corroding, aggravating cracking at the door bearing points. Repairs are required in the short term to address deterioration of the of the concrete block walls.

Photograph 5.2.1.3-1: Mortar joint deterioration of exterior concrete block walls.



Photograph 5.2.1.3-2: Mortar joint deterioration of exterior concrete block walls.





Photograph 5.2.1.3-3: Mortar joint deterioration of exterior concrete block walls.



Recommendation 5.2.1.3-1: The exterior concrete block walls are in fair to poor condition. Repairs are required in the short term to address deterioration of the mortar joints and masonry control joints.

Estimated Cost: \$150,000

Priority: Short Term, recommended within 1 year.

- .4 Cracking and delamination of the structural concrete slab at the northwest corner adjacent to the snow melt pit was observed (Photograph 5.2.1.4-1 and Photograph 5.2.1.4-2). Repairs are required in the short term.

Photograph 5.2.1.4-1: Surface deterioration around snow melt pit. Concrete deterioration along joint and door sill.





Photograph 5.2.1.4-2: Cracking in Zamboni storage room slab.



Recommendation 5.2.1.4-1: Installation of protective measures such as a penetrating silane sealer or waterproofing membrane should be considered in the long term.

Estimated Cost: \$8,000.

Priority: Long Term, recommended within 5 to 10 years.

- .5 The existing precast concrete bleachers are in good condition. A crack was observed at joint between concrete bleachers and landing at the northeast corner (Photograph 5.2.1.5-1). The cracking is likely related to restrained shrinkage. The conditions do not represent a structural problem and no repairs are currently recommended.

Photograph 5.2.1.5-1: Crack at joint between concrete bleachers and landing.





- .6 Corrosion of metal roof deck was observed in mechanical room at the north end of the building (Photograph 5.2.1.6-1). The corrosion appears to be related to sweating from the brine solution tanks.

Photograph 5.2.1.6-1: Corrosion of metal deck in mechanical room at the north end of the building.



Recommendation 5.2.1.6-1: Removal of the corrosion and painting of the deck is recommended to address existing corrosion.

Estimated Cost: \$2,000.

Priority: Short Term, within 1 year.

Recommendation 5.2.1.6-2: A review of the existing mechanical equipment by a mechanical consultant is recommended to determine if the existing brine tanks are contributing to observed sweating.

Estimated Cost: \$1,500

Priority: Short Term, within 1 year.

- .7 The steel framing supporting the dasher boards have minor to moderate corrosion at the base (Photograph 5.2.1.7-1). Periodic repairs and painting will be required.



Photograph 5.2.1.7-1: Corrosion on dasher board framing.



Recommendation 5.2.1.7-1: Periodic repairs and painting will be required.

Estimated Cost: N/A – Non-capital Expense

Priority: Maintenance.

5.3 Building Envelope

5.3.1 Walls and Cladding

- .1 The exterior concrete block walls are in fair to poor condition with select areas showing extensive freeze-thaw deterioration. The control joint sealant in the block walls has also exceeded its useful life. Refer to Recommendation 5.2.1.3-1. The concrete block walls are painted, and many areas exhibit blistering and/or peeling. Along the east face the block was recently re-painted, and the coating is was in relatively good condition at the time of the site visit. The interior surfaces of the concrete block walls were generally in good condition.

Recommendation 5.3.1.1-1: To address moisture infiltration into the concrete block walls, installation of a highly breathable elastomeric coating be applied to the exterior block walls after completion of the repairs identified in Recommendation 5.2.1.3-1.

Estimated Cost: \$40,000.

Priority: Medium Term, within 1 to 5 years.

Recommendation 5.3.1.1-2: A substantially improvement to durability would be achieved through the application of a vapour permeable air/water barrier, insulation, and new cladding system. The insulation would help keep the block within a more consistent



temperature range, reducing the condensation potential and thus freeze-thaw damage to the block and mortar.

Estimated Cost: Costs included in Recommendation 5.3.1.2-2.

Priority: Long Term, within 5 to 10 years.

- .2 The metal panel cladding is generally in good condition; however, the coating has faded and the steel exhibits minor corrosion in select areas. The fasteners in the metal panel system exhibit corrosion in select areas. The seams on the metal panel cladding are opening due to deformation in the panels; additional fasteners are required. Along the west wall, impact damage is present along the metal liner panels, extending about 40' in length along the wall. Repairs are considered discretionary.

The interior surface of the metal liner panel is generally in good condition with only minor impact damage along the upper elevations next to the seating areas. No repairs are required.

The building envelope for the arena is currently providing sufficient environmental separation to facilitate continued operation of the building. Based on the building design and construction, the building is very poorly insulated and likely exhibits major air leakage through the exterior walls and joints, which can have a major impact on the operational costs for the building.

If the facility is expected to be used for the foreseeable future, in excess of 10 years, we recommend that consideration be given to enhancing the energy performance of the building while concurrently introducing measures that increase the durability and hence the effective service life of the building.

Recommendation 5.3.1.2-1: Provide additional fasteners to the metal cladding system to ensure the cladding is sufficiently secured to the structural back-up.

Estimated Cost: \$10,000.

Priority: Short Term, within 1 year.

Recommendation 5.3.1.2-2: Long term recommendations consist of the removal of the metal panel to expose the interior metal liner panel so that a membrane can be applied over the joint seams. Insulation can then be applied to increase the thermal resistance followed by new cladding.

Estimated Cost: \$1,500,000.

Priority: Long Term Considerations.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

- .3 At the time of the site visit, the rainwater leaders at the base of the wall are covered with piled snow reducing the ability to shed accumulating moisture. Regular exposure to water is saturating the wall and hastening freeze-thaw deterioration to the block walls.

Recommendation 5.3.1.3-1: Remove snow accumulating in front of rainwater leaders during winter months.

Estimated Cost: N/A – Non-capital Expense

Priority: Maintenance.

5.3.2 Roof

Arena Roof

- .1 Roof R1 is a 4-ply asphalt gravel built up roof assembly (Photograph 5.3.2.1-1).
- The existing membrane shows multiple roof cover splits (Photograph 5.3.2.1-2).
 - Areas of the asphaltic membrane are exposed throughout the roof (Photograph 5.3.2.1-3)
 - The gutters are filled with gravel (Photograph 5.3.2.1-3).
 - The asphaltic roof cover is brittle and dried out.

Overall the roof cover is in poor condition and has exceeded its useful life-expectancy.

Photograph 5.3.2.1-1: Showing R1 roof, view of arena.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374


Photograph 5.3.2.1-2: Showing on R1 split in asphaltic roof cover.



Photograph 5.3.2.1-3: Typical exposed asphaltic membrane.



Photograph 5.3.2.1-3: View of gravel filled gutter on arena.





Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Recommendation 5.3.2.1-1: Roof R1 is in poor condition and has reached the end of its useful service life. Based on the age and condition of the membrane, replacement is recommended in the short term.

Estimated Cost: \$217,000

Priority: Short Term, within 1 year.

Roof R2

.2 Roof R2 is SBS 2-ply modified bitumen roof membrane (Photograph Photograph 5.3.2.2-1).

- The open areas and noted the field and flashing membrane are in good condition.
- Existing slope is satisfactory for water run off towards the 2 scuppers.

Overall the membrane is performing as intended. The roof slope is adequate, and water runoff is accommodated by primary internal drains and secondary scuppers. The membrane flashing assemblies on the parapets, roof wall interface, and roof penetration are in good order. We do not anticipate that replacement of roof R2 will be required in the timeframe considered in this report. Regular maintenance is recommended to ensure the membrane will reach its full life cycle potential.

Photograph 5.3.2.2-1: SBS modified bitumen roof type, R2.



Recommendation 5.3.2.2-1: Annual maintenance required.

Estimated Cost: N/A – Non-capital expense.

Priority: Annually, 12 months.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Roof R3

- .3 Roof R3 is a metal roof panel system (Photographs 5.3.2.3-1 and Photograph 5.3.2.3-2). The existing roof is in good condition. Typically, a metal roof cover can provide approximately 45 to 50 years of service. At the time of the visit we observed minor repairs as expected for the age of the panels. No rust or major defects were found. We do not anticipate that replacement of roof R3 will be required in the timeframe considered in this report. Further maintenance and roof reviews in the future shall suffice.

Photograph 5.3.2.3-1: R3 roof type. Metal standing seam roof.



Photograph 5.3.2.3-2: Typical repair on a metal panel.



Recommendation 5.3.2.3-1: Annual maintenance required.

Estimated Cost: N/A – Non-capital expense.

Priority: Annually, 12 months.



6. Estimates of Probable Construction Costs

The following table summarizes our estimate of probable construction costs by category. All costs presented are in 2019 dollars and are before taxes, contingencies, and consulting fees.

Table 1 – Required Repairs (within 3 months)

Category	Section	Recommendation	Description	Estimate
Required Repairs	Structural	3.2.4.2-1	Repair fixed access roof ladders	\$5,000
		4.2.3.1-1	Upgrade mezzanine guardrail	\$10,000
		4.2.5.2-1	Repair fixed access roof ladders	\$5,000
Total Required Repairs (within 3 months)				\$20,000

Table 2 – Short Term Recommendations (within 1 year)

Category	Section	Recommendation	Description	Estimate
Short Term	Site	3.1.1.2-1	Repairs to south entrance landing	\$18,000
		4.1.1.1-1	Repairs to exterior sidewalks and curbs	\$15,000
		4.1.1.2-1	Repairs to west entrance landing	\$3,000
		4.1.2.2-1	Re-grading of existing sod	\$5,000
		5.1.1.1-1	Localized concrete repairs	\$5,000
	Structural	3.2.1.3-1	Structural assessment of basement wall	\$5,000
		3.3.1.1-1	Precast panel repairs	\$15,000
		3.3.1.2-1	Precast panel joint repairs	\$3,000
		4.2.2.1-1	Pool tank concrete repairs	\$80,000
		4.2.2.1-2	Structural assessment	\$10,000
		4.2.2.2-2	Pool tank crack injection	\$15,000
		5.2.1.1-1	Arena crawlspace remediation	\$670,000
		5.2.1.1-2	Mechanical assessment	\$10,000
		5.2.1.2-1	Rink slab concrete repairs	\$380,000
		5.2.1.2-2	Structural assessment	\$15,000
		5.2.1.3-1	Exterior concrete block repairs	\$150,000
		5.2.1.6-1	Mechanical room roof deck repairs	\$2,000
		5.2.1.6-2	Mechanical assessment	\$1,500
	Building Envelope	3.3.1.4-2	Exterior concrete block repairs	\$25,000
		3.3.3.1-1	Roof replacement	\$280,000
		4.3.3.2-1	Roof replacement	\$120,000
		4.3.3.3-1	Roof maintenance repairs	\$10,000
		5.3.1.2-1	Repair metal cladding fasteners	\$10,000
Mechanical	5.3.2.1-1	Roof R1 replacement	\$217,000	
	4.4.1.1-1	Pool exhaust	\$130,000	
		4.4.1.1-2	Replace AHU-1 ductwork	\$7,500
Total Short Term Recommendations (within 1 year)				\$2,202,000



Table 3 – Medium Term (Years 1 to 5)

Category	Section	Recommendation	Description	Estimate
Medium Term	Site	3.1.1.1-1	Repairs to asphalt paving	\$15,000
		4.1.1.1-2	Repave existing driveway	\$60,000
	Structural	3.2.2.2-1	Interior masonry repairs	\$3,000
		3.2.2.3-1	Stairwell masonry repairs	\$4,000
		3.3.1.3-1	Building envelope investigation	\$25,000
		4.2.2.2-1	Pool tank tile replacement	\$275,000
	Building Envelope	3.3.1.4-3	Re-clad east dressing room	\$100,000
		3.3.1.4-3	Re-clad west washrooms	\$100,000
		3.3.2.1-1	Replace ribbon windows	\$7,500
		4.3.1.3-1	Exterior concrete block repairs	\$45,000
		4.3.1.3-2	Re-clad west locker/washroom area	\$45,000
		4.3.2.1-1	Replace ribbon windows	\$7,500
		4.3.2.2-1	Replace south elevation upper windows	\$6,000
		4.3.2.3-1	Replace upper ribbon windows	\$4,000
		4.3.2.4-1	Entrance door/curtain wall replacement	\$20,000
		5.3.1.1-1	Elastomeric wall coating	\$40,000
	Mechanical	4.4.1.3-1	Replace HVAC and boilers	\$120,000
4.4.1.4-1		Evaluate AHU-3	\$15,000	
Total Medium-Term Recommendations (Years 1 to 5)				\$892,000

Table 4 – Long Term (Years 5 to 10)

Category	Section	Recommendation	Description	Estimate
Long Term	Structural	3.2.1.1-1	Crawlspace remediation (RC-22/PI-05)	\$350,000
		5.2.1.4-1	Zamboni room slab protection	\$8,000
	Building Envelope	4.3.1.3-1	Re-clad locker/washroom area	\$45,000
	Mechanical	4.4.1.2-1	Replace AHU-1	\$50,000
		4.4.1.8-1	Sump pumps	\$12,000
Total Long-Term Recommendations (Years 5 to 10)				\$465,000



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Table 5 – Long Term Considerations/Recommended Improvements (not time critical)

Category	Section	Recommendation	Description	Estimate
Long Term Considerations/Recommended Improvement	Structural	4.2.1.2-1	Basement slab repairs	\$5,000
		4.2.1.3-1	Boiler room slab repairs	\$3,000
		4.2.1.4-1	Air Handler room slab repairs	\$3,000
	Building Envelope	3.3.1.3-2	Re-clad Recreation Centre	\$450,000
		3.3.1.4-1	Remove wood trim at roof level	\$5,000
		4.3.1.3-2	Re-clad pool area	\$350,000
	Mechanical	5.3.1.2-2	Re-clad arena area	\$1,500,000
		4.4.1.5-1	Replace pneumatic controls	\$110,000
		4.4.1.6-1	Exhaust fans	\$9,000
		4.4.1.7-1	Replace AHU-4	\$9,000
Total Long Considerations / Recommended Improvements				\$2,444,000

Table 6 – Summary of All Recommendations

Category	Estimate
Total Required Repairs (within 3 months)	\$20,000
Total Short-Term Recommendations (within 1 year)	\$2,202,000
Total Medium-Term Recommendations (Year 1 to 5)	\$892,000
Total Long-Term Recommendations (Year 5 to 10)	\$465,000
Long Term Considerations/Recommended Improvements (not time critical)	\$2,444,000
Total of All Recommendations	\$6,023,000



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

7. Closure

At the request of the City of Winnipeg Planning Property & Development Department, a structural, building envelope, and mechanical systems assessment of the St. James Civic Centre Pool was completed by Crosier Kilgour & Partners and Epp Siepman personnel. The purpose of the investigation was to provide an opinion as to the current condition of the structure, cladding, windows and roofing, identify areas of distress, and provide recommendations for immediate, short and long-term repairs.

We trust that this report provides the information you require. Upon your review, please contact our office at your convenience to discuss this report in further detail.

Structural
CROSIER KILGOUR & PARTNERS LTD.



Derek J. Mizak, P.Eng.

Building Envelope
CROSIER KILGOUR & PARTNERS LTD.



Stephanie E. Zubriski P.Eng.
M.Sc. LEED AP BD+C

Mechanical
EPP SIEPMAN ENGINEERING



John Schellenberg, P.Eng.



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-07-08)
2019-0374

Appendix A

Thermographic Report - Recreation Centre



Report for:
Submitted to:
Date:
Our File No.

St. James Civic Centre
City of Winnipeg
June 14, 2019 (Revised 2019-09-30)
2019-0374

Appendix B

Thermographic Report - Indoor Swimming Pool