



Figure 1: View from West Side of Deacon Pump Floor



Figure 2: View of Pipe Bend Reducer and Blind Flange to be Removed





Figure 3: View of Work Area at Pipe Bend Reducer Facing North



Figure 4: View of Work Area at Pipe Bend Reducer Facing South





Figure 5: Garage Entry Gantry Crane




Figure 6: Garage Entry Access to Pump Station Floor





Figure 7 View from Garage Entry Access to Platform on Pump Station Floor below



Figure 8: Garage Door





Figure 9: View from Pump Station Walkway to Garage Access (above)



Figure 10: Pump Station Floor Platform below Garage Access





Figure 11: View from East Side of Deacon Pump Floor



Figure 12: Existing Panel PP-D30





Figure 13: Existing Panel PP-D30 Cable Tray



Figure 14: View down to location south of blinded intake piping bend





Figure 15: East site 610 mm Access Blind Flange



Figure 16: Suction Header Photo 1 circa 1995





Figure 17: Suction Header Photo 2 circa 1995