

Appendix E – Site Photos



Figure 1: AHU-1 damper manual actuator.



Figure 2: AHU-2 damper manual actuator.



Figure 3: Looking west showing three existing exhaust fan dampers (ceiling), and existing starters, wiring, conduits, pneumatic piping, and control (wall).



Figure 4: Existing exhaust fan damper and actuator - typical of three.



Figure 5: Existing starters, wiring, conduits, pneumatic piping, and control for three exhaust fans.



Figure 6: Looking east showing existing supply air fan.



Figure 7: Southeast corner of crawlspace showing existing cooling tower pipes penetrating the grade beam extension.



Figure 8: Looking west in crawlspace showing existing sump basin and piping penetrating original grade beam.




Figure 9: Existing indoor chiller, looking east.



Figure 10: Existing indoor chiller, looking southeast.



Figure 11: Existing indoor chiller, looking southwest.



Figure 12: Looking south showing existing chilled water pumps, cooling tower pumps, and expansion tank.



Figure 13: Looking east showing existing chilled water piping up to two rooftop air handling units.



Figure 14: Looking south showing existing chilled water piping up to two rooftop air handling units.




Figure 15: Looking west in the Chlorine Storage room showing existing chilled water piping roof penetrations up to two rooftop air handling units.



Figure 16: Existing cooling tower.



Figure 17: Site access, looking south.



Figure 18: Site access, looking east.




Figure 19: Existing MCC-1 labels.




Figure 20: Existing MCC-2 labels.