


- ① Re-install existing steel framing, thru bolts & lag bolts
- ② Install new cap flashing
 - install new cap flashing
 - 18 Ga prefinished metal (color selected by owner)
 - caulk all joints
- ③ Remove temporary shoring

NEW GLULAM BEAM REPAIRS

Scale: 1/2" = 1'-0"



SK-16

Gulam Beam Repairs
 St Vital Arena
 580 St. Annes Road
 Winnipeg, MB R2M 3G4



GC ENGINEERING LTD.
 675 ELM ST.
 WINNIPEG MB R3M 3N8
 PH 793-3948 FAX 487-4616
 EMAIL CALGRAY@MTS.NET