

APPENDIX 'C'

Photo Log

APPENDIX 'C' – PHOTO LOG



Photo 1: Looking south on St. Mary's from Vivian intersection (August 31, 2022)



Photo 2: Looking north on St. Mary's from Vivian intersection (August 31, 2022)



Photo 3: Looking south on St. Mary's at closed sidewalk segment (July 12, 2022)



Photo 4: Looking upstream at the top of bank near the upstream edge of the project area (July 12, 2022)



Photo 5: Looking south on St. Mary's. Utilities marked out on sidewalk (July 29, 2022)



Photo 6: Looking south on St. Mary's at closed sidewalk segment after a rain event. CB at failure not low spot with ponding occurring in gutter (October 14, 2022)



Photo 7: Looking south on St. Mary's at closed sidewalk segment. Significant undermining (July 12, 2022)



Photo 8: Close-up view of upper bank failure undercutting the sidewalk (July 12, 2022)



Photo 9: Looking downstream at the top of bank near the upstream edge of the project area (July 12, 2022)



Photo 10: Potential site access. Looking upstream at the top of the bank showing the barricaded failed sidewalk (July 12, 2022)



Photo 11: Looking upstream at mid-bank (approx. OHWM) near the upstream edge of the project area (July 12, 2022)



Photo 12: Looking downstream at mid-bank (approx. OHWM) near the middle of the project area (July 12, 2022)



Photo 13: Looking upstream at toe of bank (water approx. 224 m) near the upstream edge of the project area (July 12, 2022)



Photo 14: Looking downstream at toe of bank (water approx. 224 m) near the upstream edge of the project area (July 12, 2022)



Photo 15: Looking upstream at toe of bank (water approx. 224 m) near the downstream edge of the project area (July 12, 2022)



Photo 16: Looking downstream at toe of bank (water approx. 224 m) near the downstream edge of the project area (July 12, 2022)



Photo 17: Location of top of construction access ramp at 480 St. Mary's Road. (December 1, 2022)



Photo 18: Looking south near top of construction access ramp. Caution must be exercised around existing signs and utilities (December 1, 2022)



Photo 19: Looking upslope from bottom of construction access ramp. Site must be secured with fencing. Refer to tree protection specifications. (December 1, 2022)



Photo 20: Looking upstream from bottom of construction access ramp. (December 1, 2022)



Photo 21: Old concrete block (to be removed) marks the downstream limit of riprap (refer to drawings for details). (December 1, 2022)



Photo 22: Looking upstream from old concrete block (to be removed). (December 1, 2022)



Photo 23: Looking downstream from concrete slab (old boat launch to be removed) . (December 1, 2022)



Photo 24: Looking downstream at toe of riverbank (water approx. 222 m) (December 1, 2022)