The City of Winnipeg Addedum 1 - Appendix C RFP No. 926-2019 Page 1 of 1

Template Version: SrC120190115 - Consulting Services RFP

APPENDIX C (R1) - 2019 Sewer Renewals and External Point Repairs - Contract 1 - Table A

| ASSET | STREET NAME | LOCATION DETAILS | SPG | DIA. | WORK TYPE | START | FND | LENGTH | PROGRAM COST | COMMENTS |
|--------------|--------------------------|---|-----|------|-----------------------------|-------|-------|--------|--------------|--|
| | 8 FORKS MARKET RD | | 3 | | ABANDON MANHOLE | | | 1 | | MH SERVES NO PURPOSE. NO PIPES ENTERING OR LEAVING. |
| | | | | | | | | | . , | "2016 PW STREET WORK ABANDONING CB LEADS AT U/S PORTION OF SEWER. NO OTHER |
| | | | | | | | | | | CONNECTIONS TO MAIN, SO THIS WILL BE ABANDONED ALSO LINE WASN'T ABANDONED IN |
| S-MA00009266 | AIKINS ST | MH AT POLSON AV TO PLUG N OF POLSON AV | 5 | 250 | 7-ABANDON SEWER | 0 | 18.8 | 18.8 | \$10,000.00 | 2016 PW JOB ADDED TO 2019 CAPITAL SEWER PROGRAM" |
| S-MA00012697 | AIKINS ST | MH AT CATHEDRAL AV TO MH AT MACHRAY AV (CL) | 4 | 600 | 6-EXTERNAL POINT REPAIRS | 74.1 | 76.1 | 2 | \$16,400.00 | Void @ Service |
| S-MH20014508 | ALBERT ST | 1ST MH S OF MCDERMOT AV | 4 | 0 | 1 - STABILIZATION | | | 1 | | GROUT MH BASE TO REPAIR MISSING BRICKS |
| | | | | | | | | | | |
| S-MH50008628 | ARCHIBALD ST | 2ND MH S OF PLINGUET ST | 4 | 0 | 7 - REPAIR/REPLACE BENCHING | | | 1 | \$400.00 | MH HAS NO BOTTOM |
| S-MA40000619 | BACKLANE N OF ESSAR AV | 1ST MH W OF APPLETON ST TO UNKNOWN ASSET | 4 | 1050 | 6-EXTERNAL POINT REPAIRS | 45 | 48.25 | 3.25 | \$29,850.00 | |
| S-MA70015648 | EASEMENT | MH AT CARRIAGE RD-MH AT VALLEY VIEW DR | 3 | 250 | 6-EXTERNAL POINT REPAIRS | 28.4 | 32.4 | 4 | \$17,500.00 | DIP IN LINE - HISTORY OF SEWER BACKUP |
| S-MH20012218 | HIGGINS AV | MH AT INTERSECTION OF HIGGINS AV & ARGYLE ST | 4 | 0 | REPLACE MANHOLE | | | 1 | \$31,040.00 | FULL MH REPLACEMENT REQUIRED |
| S-MA20004598 | KEATS WY | 2ND MH W OF BEDSON TO MH AT BEDSON | 5 | 300 | 6-EXTERNAL POINT REPAIRS | 37.2 | 38.7 | 1.5 | \$13,750.00 | DEFORMED - FOUR POINT HINGE FRACTURES |
| | | | | | 5-FULL SEGMENT REPLACEMENT | | | | | |
| S-MA50013595 | KINGSTON RW | 2ND MH W OF MAGER DR W TO 1ST MH W OF MAGER | 4 | 300 | (RENEWAL) | 0 | 107.5 | 107.5 | \$165,125.00 | |
| S-MH20017293 | LIZZIE ST | MH AT LOGAN AV(N PL) | 5 | 0 | REPLACE MANHOLE | | | 1 | \$31,100.00 | "FL, DB, MD, WALL BULGING" |
| S-MA20019676 | LOGAN AV | 1ST MH E OF MAUDE ST TO NODE AT MAUDE ST | 4 | 500 | 6-EXTERNAL POINT REPAIRS | 50 | 54 | 4 | \$17,500.00 | JDL |
| S-MH20017327 | MARTHA ST | 1ST MH N OF LOGAN AV | 5 | 0 | REPLACE MANHOLE | | | 1 | \$31,200.00 | "MB, DB, FL, B, SSS" |
| S-MA20000077 | NESS AV | MH ATVALLEY VIEW DR TO 3RD MH W OF VALLEY VIEW D | 4 | 1050 | 6-EXTERNAL POINT REPAIRS | 63.5 | 66 | 2.5 | \$32,250.00 | |
| S-MA20000077 | NESS AV | MH ATVALLEY VIEW DR TO 3RD MH W OF VALLEY VIEW D | 4 | 1050 | 6-EXTERNAL POINT REPAIRS | 51.9 | 53.6 | 1.7 | \$29,890.00 | |
| | | | | | | | | | | "FC, FL, B, D, H - images available - WORK DELAYED - DRIVER DEFECT ADDRESSED BY COW IN |
| S-MA20005586 | PALLISER AV (S LEG) | 2ND MH W OF MOUNT ROYAL RD TO 1ST MH W OF MOUNT ROYAL R | 5 | 300 | 6-EXTERNAL POINT REPAIRS | 0 | 24.2 | 24.2 | \$47,800.00 | 2002. |
| | | | | | | | | | | ACTUAL END DISTANCE UNKNOWN - REVERSAL NOT POSSIBLE TIES INTO DOWNSTREAM MH |
| S-MA70019573 | PLINGUET ST | MH AT LAURIER ST TO NODE AT DAWSON RD N (N OF CL) | 5 | 375 | 6-EXTERNAL POINT REPAIRS | 106.1 | 109.1 | 3 | \$16,000.00 | WITH A TEE |
| S-MA70035769 | PORTAGE AV E | 1ST MH W OF WESTBROOK ST TO MH AT WESTBROOK ST | 5 | 300 | 6-EXTERNAL POINT REPAIRS | 0 | 3 | 3 | \$15,700.00 | |
| | | | | | | | | | | "CROSS BORE AT 72.0m (NO SCORE GIVEN, DOES NOT APPEAR IN CONDITION SUMMARY), |
| S-MA20000438 | PORTAGE AVE(N OF N CURB) | MH AT SUMACH ST-1ST MH E OF SUMACH ST | 5 | 2400 | 6-EXTERNAL POINT REPAIRS | 71.5 | 72.5 | 1 | \$36,000.00 | BELIEVED TO BE HYDRANT LEAD (ASSET # W-HY20000556)" |
| S-MA50005275 | ROYAL SALINGER RD | MH AT NIAKWA RD TO OUTLET OF FERMOR AV | 5 | 400 | 6-EXTERNAL POINT REPAIRS | 27.9 | 29.7 | 1.8 | \$14,200.00 | Н |
| | | | | | | | | | | |
| S-MA20016836 | SARGENT AV (N OF CL) | 1ST MH E OF FURBY ST TO 1ST MH W OF SPENCE ST | 4 | 1350 | 1-STABILIZATION (MAN ENTRY) | 38.6 | 38.8 | 0.2 | \$400.00 | HOLE AT 38.7M US OF MH20015203 AND AREAS OF INFILTRATION (19.7M US AND 27.6M US) |
| | | | | | | | | | | SEWER WAS LOOKED AT IN 2018 SEWER CONDITION ASSESSMENT PROJECT AND WAS |
| | | | | | | | | | | DETERMINED TO BE PLUGGED AT THE SRS MH. THIS WORK ORDER IS TO FILL AND ABANDON |
| S-MA20014610 | SHERBROOK ST | 3RD MH N OF PORTAGE AV TO 2ND MH N OF PORTAGE AV | 3 | 375 | 7-ABANDON SEWER | 0 | 4.07 | 4.07 | \$10,000.00 | ASSET PROPERLY. |
| | | | | | | | | | | PIPE PATCH IF SERVICE IS ABANDONED OR EPR IF SERVICE IS LIVE OR PIPEPATCH DOESN'T |
| S-MA20014204 | SMITH ST | MH AT BROADWAY (S PL) TO 1ST MH S OF BROADWAY | 4 | 750 | 6-EXTERNAL POINT REPAIRS | 53.8 | 55.8 | 2 | \$16,400.00 | WORK IN 750mm PIPE FAILED SERVICE |
| | | | | | | | | | | |
| S-MA70137338 | SOUTHWOOD AV CL | 2ND MH E PEMBINA HWY -PLUG W MH60015012 | 3 | 200 | 7-ABANDON SEWER | 0 | 2 | 2 | \$10,000.00 | ASSET ISN'T IN GREAT SHAPE AND HAS NO USE. THE 2 CONNECTIONS TO IT ARE CAPPED. |
| | | | | | 5-FULL SEGMENT REPLACEMENT | | | | | 20% DEFORMATION MEANS LINING WOULD REQUIRE AN EPR ANYWAYS AND BECAUSE ASSET |
| S-MA20014753 | SPENCE ST (CL) | 3RD MH S OF ST MARY AV TO 4TH MH S OF ST MARY AV | 4 | 300 | (RENEWAL) | 0 | 3.5 | 3.5 | \$24,725.00 | IS ONLY 3 METRES LONG IT MAKES SENSE TO JUST REPLACE |
| | | | | | | | | | | |
| S-MA20010497 | ST JAMES ST | 1ST MH S OF SASKATCHEWAN AV TO 2ND MH S OF SASKATCHEWAN / | 4 | 375 | 6-EXTERNAL POINT REPAIRS | 65.1 | 66.1 | 1 | . , | POORLY INSTALLED CONNECTION. APPEARS TO BE POSSIBLE VOIDING OUTSIDE OF MAIN. |
| | | | | | | | | | | SERVICE CONNECTION AT 32.2m HAS VISABLE VOIDING. MAY BE ABLE TO REPAIR SERVICE VIA |
| S-MA20017544 | VICTOR ST | 1ST MH N ELLICE AV TO MH AT ELLICE AV (CL) | 4 | 600 | 6-EXTERNAL POINT REPAIRS | 31.6 | 32.8 | 1.2 | . , | SADDLE CONNECTION WITH A CONCRETE COLLAR. |
| | | | | | | | | | _ | CODING SHOWS NO SERVICES ARE CONNECTED. APPEARS TO NOT SERVE ANY PURPOSE. ROAD |
| S-MA70137792 | | 2ND MH W DUNKIRK DR - UNKNOWN ENTITY | _ | | 7-ABANDON SEWER | 0 | 1.1 | 1.1 | . , | REHAB PROBABLY HAPPENING IN 2019. |
| S-MH20017100 | WILLIAM AV | MH AT WILLIAM AV AND HARGRAVE ST | 5 | 0 | REPLACE MANHOLE | | | 1 | \$29,500.00 | "FRSS MH C&F CL, SSM ON RISER, FC, FL ON REDUCER, SSL ON BENCHING" |
| C 144=000==: | 14//14/4/4/4 22 | AND AT COPERS OF (CI) TO AND AT COPERS OF (CI) | _ | | 5-FULL SEGMENT REPLACEMENT | | 40.0 | | A.= c= . r= | |
| S-MA50005711 | WINAKWA RD | MH AT SPEERS RD (CL) TO MH AT SPEERS RD (W PL) | 5 | 200 | (RENEWAL) | 0 | 18.8 | 18.8 | \$45,384.05 | |
| | | | | | | | | | | |