APPENDIX 'C'

DILLON CONSULTING LIMITED FIELD EXCAVATION PHOTOGRAPHS -MARCH 23, 2009



Looking east at area to be excavated. Note proximity of existing retaining wall. 2008-03-23_Field Excavation_P001 Looking west at area to be excavated. 2008-03-23_Field Excavation_P002



Looking south at area to be excavated along east retaining wall alignment. 2008-03-23_Field Excavation_P003 Looking east at area just prior to excavation. 2008-03-23_Field Excavation_P004



Looking north at excavated area. 2008-03-23_Field Excavation_P005

Looking north at excavated area. Note concrete slabs approximately 200 mm thick. 2008-03-23_Field Excavation_P006



Looking south at excavated area. 2008-03-23_Field Excavation_P007

Looking south at excavated area. Note concrete slabs. 2008-03-23_Field Excavation_P008



Looking south at excavated area. 2008-03-23_Field Excavation_P009

Looking south at excavated area. 2008-03-23_Field Excavation_P010



Looking south at excavated area. Note abandoned steel pipe. 2008-03-23_Field Excavation_P011 Looking west at excavated area adjacent existing retaining wall. 2008-03-23_Field Excavation_P012



Looking south at excavated area (2 m wide x 4 m long x 3 m deep) adjacent existing retaining wall. 2008-03-23_Field Excavation_P013



Looking south at excavated area. Note foundation wall beneath existing retaining wall approximately 2.5m deep. 2008-03-23_Field Excavation_P014