



PHOTOGRAPH 7: ZONE G, FACING NORTH, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON LEFT SIDE OF PICTURE.



PHOTOGRAPH 8: ZONE G, FACING SOUTH, SHOWING BUNN'S CREEK SHORLINE AND CHANNEL.



PHOTOGRAPH 9: ZONE H, FACING WEST, SHOWING FAILED REGION AT TOP OF BANK.



PHOTOGRAPH 10: ZONE H, FACING SOUTH, SHOWING STEEP INCLINE FROM TOP OF BANK (PATHWAY) TO CREEK SHORELINE AT FAILED REGION.



PHOTOGRAPH 11: ZONE I, FACING WEST, SHOWING PATHWAY AND BUNN'S CREEK LOCATED ON LEFT SIDE OF PICTURE.



PHOTOGRAPH 12: ZONE J, FACING NORTHWEST, SHOWING BUNN'S CREEK SHORELINE AND CHANNEL.

No.	DATE	ISSUE /REVISION
0	Aug 2015	Report/ Tender

**ENG-TECH**  
CONSULTING LIMITED  
6 - 854 Marion Street  
Winnipeg, MB R2J 0K4  
Phone: (204) 233-1694  
Fax: (204) 235-1579

ENG. STAMP:  
**APEGM**  
Certificate of Authorization  
ENG-TECH Consulting Limited  
No.2475 Expiry: April 30, 2016

CLIENT:  
DEAN SPEARMAN LANDSCAPE  
ARCHITECT

PROJECT:  
SLOPE STABILITY ASSESSMENT AND  
EROSION PROTECTION, BUNN'S  
CREEK PATHWAY, WINNIPEG, MB

DWG DESCRIPTION:  
PHOTOGRAPHS 7 TO 12

SCALE:  
N/A

DRAWN BY: ERM	DATE: AUGUST 2015
------------------	----------------------

FILE No.:	CLIENT DWG/FIG. No.:
15-330-01	

ENG-TECH DWG/FIG. No.:	No.:
G11	