

**APPENDIX B - TABLE E8.2 : SITE SPECIFIC MANHOLE CONDITIONS AND REPAIR REQUIREMENTS**

	<b>STREET_NAME</b>	<b>LOCATION_DETAILS</b>	<b>MANHOLE_ID</b>	<b>REPAIRS REQUIRED</b>
1	Ellice Avenue	MH at Agnes Street	S-MH20014723	Grout 0.1m risers under frame
2	Ellice Avenue	1st MH W of Agnes Street	S-MH70008168	Grout 0.1m risers under frame
3	Emily Street	1st MH S of McDermot Avenue	S-MH20016378	Replace cover
4	Mount Royal Road	MH at Harmon Avenue	S-MH20004675	Grout 0.3m risers under frame, install benching
5	Mount Royal Road	MH at Lodge Avenue	S-MH20004676	Grout 0.1m risers under frame, grout hole 1.0m below frame, install benching
6	Higgins Avenue	MH at Sutherland Avenue E of PL	S-MH70000474	Grout 0.45m risers uneder frame