


VERTICAL TEE


VERTICAL CROSS

VERTICAL ELL






FLAT CROSS



FLAT ELL

- 1. JOIN WATERSTOP TO FORM A CONTINUOUS UNBROKEN WATERSEAL.
- 2. ASSEMBLE 'TEES', 'CROSSES', AND 'ELLS' ACCURATELY.
- 3. WELD STRAIGHT BUTT SPLICE WATERSTOP IN ACCORDANCE WITH MANUFACTURER'S WRITTEN INSTRUCTIONS.
- 4. WELD TO PENETRATE FULL DEPTH OF THE WATERSTOP MATERIAL AT SPLICES.





FLAT CROSS

MITER CORNERS OF VERTICAL

JOINTS & WELD SIMILAR AS


## NOTE:

FLAT ELL

ALL WELDS SHOWN SHALL BE BY WATERSTOP MANUFACTURER (SEE SPECIFICATIONS)

FLAT TEE





#### NOTES:

PLACEMENT SEQUENCE SHOWN REQUIRED ON BOTH SIDES OF JOINTS, IN ALL CONCRETE SLAB AND FOOTING POURS WITH HORIZONTALLY PLACED PLASTIC WATERSTOPS.

#### STEP 1

PLACE CONCRETE BELOW WATERSTOP FIRST, REMOVE ALL AIR VOIDS BY VIBRATING

#### THOROUGHLY. STEP 2

TO CONFIRM THERE ARE NO AIR VOIDS, LIFT WATERSTOP. A CONTINUOUS IMPRESSION OF THE WATERSTOP, INCLUDING EDGE OF BULB, SHOULD BE VISIBLE IN THE FRESH CONCRETE. CONTINUE THIS PROCEDURE ALONG THE ENTIRE POURED JOINT, END TO END. IF A CONTINUOUS IMPRESSION IS CONFIRMED, PROCEED WITH STEP 4. IF A VOID LARGER THAN 6mm IN DIAMETER IS PRESENT ANYWHERE IN THE WATERSTOP IMPRESSION, PROCEED WITH STEP 3.


### STEP 3

IF A VOID LARGER THAN 6mm IN DIAMETER IS PRESENT IN THE WATERSTOP IMPRESSION, ADDITIONAL CONCRETE SHALL BE PLACED UNDER THE WATERSTOP, VIBRATED, AND STEP 2 REPEATED.


#### STEP 4

FINISH PLACING CONCRETE ABOVE THE WATERSTOP TO TOP OF SLAB.






TYPICAL CURB





CURB FOR CMU WALLS













1. FIELD VERIFY LOCATIONS PRIOR TO FABRICATION. COORDINATE w/ MECHANICAL SUCONTRACTOR.


# LIFTING EYE SUPPORT

LIFTING EYE





CONCRETE STAIR - WITHOUT CLOSURE WALL N.T.S.





SODIUM HYPOCHLORITE BUILDING SODIUM HYPOCHLORITE AND CHEMICAL STORAGE BUILDINGS

STRUCTURAL SODIUM HYPOCHLORITE BUILDING STANDARD DETAILS