

A

1

power wire brush clean top of existing glulam beam
(to be inspected prior to new repairs installed)

new 2x12 (DF #1) laminations

2'-2"±

1'-5 5/8"

4 7/8"

4 7/8"±

6"

8"

8"

6"

1'-15 5/8"

8" min staggered joints

random repairs to be determined on site

- route out existing lamination to solid wood
- install similar sized lamination (DF #1) c/w epoxy resin adhesive

New Glulam Beam Repair Methods

Scale: 1" = 1'-0"

SK-5

Glulam Beam Repairs
 Terry Sawchuk Arena
 901 Kimberley Ave
 Winnipeg, MB R2K 4B9



GC ENGINEERING LTD.
 675 ELM ST.
 WINNIPEG MB R3M 3N8
 PH (204) 793-3948
 EMAIL CALGRAY@LIVE.CA