



1019-2014 ADDENDUM 1

REPAIR OF SODIUM HYDROXIDE STORAGE TANK

URGENT

**PLEASE FORWARD THIS DOCUMENT TO
WHOEVER IS IN POSSESSION OF THE BID
OPPORTUNITY**

ISSUED: November 13, 2014
BY: Roberta Cameron
TELEPHONE NO. (204) 986-2233

**THIS ADDENDUM SHALL BE INCORPORATED
INTO THE BID OPPORTUNITY AND SHALL
FORM A PART OF THE CONTRACT
DOCUMENTS**

Template Version: A20131129

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.

PART E – SPECIFICATIONS

- Revise: E1.1 (c) to read: Repair the tank liner by grinding the sections affected to remove the dried out layer. Reline the surface with 2 plies of 1.5 ounce per square foot chopped strand mat and **2 plies** of Nexus® Synthetic Veil using premium vinyl ester resin, Derakane Momentum 411-350. Resin-rich flood coat the repaired liner with Derakane Momentum 411-350 complete with paraffin wax (Air Dry). Post cure the tank for a barcol hardness of over 35.
- Revise: E1.3 to read: Bidders are reminded that requests for approval of substitutes as an approved equal or an approved alternative shall be made in accordance with **B7**.