


EPOXY INJECTION & WOOD

FILLET REPAIR SECTION

S4.2 S4.2 1-1/2" = 1'-0"



TYPICAL GLULAM

ROT & CRACK REPAIR

| S2.1 | S4.2 | 1-1/2" = 1'-0"

The General Contractor shall check & verify all dimensions and report any errors or omissions to the designers.


O 2017-04-19 ISSUED FOR CONSTRUCTION SMONO. Date Issue/Revision By

APEGIN

Certificate of Authorization

Crosier Kilgour & Partners Ltd.

No. 235 Date: 2017-04-19



Conculto

300-275 Carlton Street Winnipeg, Manitoba R3C 5R6 T 204. 943. 7501 F 204. 943. 7507

Crosier Kilgour
& Partners Ltd.
CONSULTING STRUCTURAL ENGINEERS

BERTRAND ARENA

GLULAM REPAIRS

294 BERTRAND STREET

WINNIPEG, MANITOBA
Sheet Title

SECTIONS

2017 0000

2017-0006 2017-04-19

Design SMC RJM

Revision

\$4.2