ASSET NUM	STREET	LOC DESC	FLOW TYPE	DIA MATERIAL SPG	REPAIR TYP	TOTAL LEN	START LEN RE	EPAIR LEN	EST COST COMMENTS
S-MA20016813	BALMORAL ST	MH AT SARGENT AV(SPL) TO 1ST MH S OF SARGENT AV	CS	375 *UNKNOWN	4 EXTERNAL PT REPAIR		72.1	2	\$17,000.00
S-MA20017857		3RD MH N.OF WELLINGTON AV. TO 2ND MH N.OF WELLINGTON AV.	CS	300 *UNKNOWN	5 EXTERNAL PT REPAIR		73.4	1.4	\$15,000.00 HVV, BVV, DR
S-MA20017857		3RD MH N.OF WELLINGTON AV. TO 2ND MH N.OF WELLINGTON AV.	CS	300 *UNKNOWN	5 EXTERNAL PT REPAIR		0	1.4	
S-MA20017346		MH AT SARGENT AV TO 1ST MH N.OF SARGENT AV	CS	450 *UNKNOWN	5 EXTERNAL PT REPAIR		0	5	\$26,500.00 HSV, B, JOL, FM
S-MA20017346		MH AT SARGENT AV TO 1ST MH N.OF SARGENT AV	CS	450 *UNKNOWN	5 EXTERNAL PT REPAIR		49.1	3.4	\$25,000.00 B, FM
									Wastewater services requested that we replace the tee (TE-
S-MA40006942	CANTERBURY PL	1ST MH W OF HENDERSON HWY TO MH AT HENDERSON HWY	cs	250 CONCRETE	3 INSTALL MANHOLE		129.2	131.2	40002205) with a manhole
S-MA20012090		1ST MH E OF BLAKE ST-MH @ BLAKE ST	CS	300 *UNKNOWN	5 EXTERNAL PT REPAIR	77.02			\$16,000.00 B, HSV, SAP
							-		HVV from 3 to 5 o'clock, SAM from 2 to 10 o'clock, FM from 7 to 5
									o'clock.
									Damage contained throughout last two pipe lengths. Proximity to
S-MA20012780	CLIFTON ST. N.	3RD MH S.OF NOTRE DAME AV. TO 2ND MH S.OF NOTRE DAME AV.	CS	450 *UNKNOWN	4 EXTERNAL PT REPAIR		42	2.5	\$18,500.00 gas main
									freezing issues. Pipe needs insulation because the sewer is too
S-MA50014542	FITZPATRICK RD	1ST MH N OF WORTHINGTON AV -MH AT WORTHINGTON AV	wws	250 CONCRETE	2		0	101.931	\$157,600.00 shallow.
							-		
S-MA20019657	HILLOCK AV	1ST MH W OF MCPHILLIPS TO MH AT MCPHILLIPS (WPL)	CS	375 *UNKNOWN	4 EXTERNAL PT REPAIR	68.91	53	3.5	\$14,600.00 FL/B/D<10% - IMAGES AVAILABLE. Close proximity to feeder main
									Upsize to 250mm. Renewal of S-MA60019517 and S-MA60019903
									required to resolve flow issues at Vassar and Linacre. See email
S-MA60019903	LINACRE RD (N LEG)	1ST MH W OF VASSAR RD TO MH AT CORNELL DR	wws	250 CONCRETE	3 FULL SEGMENT RENEWAL		0	75.036	\$123,800.00 from Akrishka on Sept 21, 2022.
									Upsize to 250mm. Renewal of S-MA60019517 and S-MA60019903
									required to resolve flow issues at Vassar and Linacre. See email
S-MA60019517	LINACRE RD N LEG	MH AT VASSAR RD TO 1ST MH W OF VASSAR RD	wws	200 CONCRETE	3 FULL SEGMENT RENEWAL		0	50.117	
	MEADOWLARK PL	1ST MH N.OF BOOTH DR. TO MH AT BOOTH DR.	LDS	450 CONCRETE	4 EXTERNAL PT REPAIR		36.9		\$17,500.00 HSV, BSV, DR
	-								FL, CL, D 5%
S-MA00012086	MINNIGAFFE ST	2ND MH S CHURCH AVE TO MH AT MOUNTAIN AVE	CS	375 CLAY	4 EXTERNAL PT REPAIR	103.12	51.7	2.3	\$23,500.00 2 service reconnects
S-MA50004764		1ST MH W. OF RUE DES MEURONS TO MH AT RUE ST.JEAN BAPTISTE		375 CLAY	5 EXTERNAL PT REPAIR		105		
									URGENT REPAIR - X, HVV, B, DR 5-20%, FM, FL, CM, CL, CC, RPLX2
									REPLACEMENT COULD BE BROKEN DOWN TO SEPERATE EPR'S IF
									DEEMED NECESSARY
									0.0m-47.1m (47.1m) Good Pipe
									47.1m-67.9m (20.8m) Bad Pipe
									67.9m-70.9m (3.0m) Good Pipe
S-MA70029542	PROVENCHER BV,	MH AT RUE AULNEAU TO MH AT RUE ST. JOSEPH	CS	450 CLAY	5 FULL SEGMENT RENEWAL		47.1	70.9	\$156,800.00 - 68.2m-69.8m CIPP Lined
	PROVENCHER BV.	MH AT RUE JOSEPH TO 1ST MH W.OF RUE JOSEPH	CS	450 CLAY	4 FULL SEGMENT RENEWAL		52.4		\$110,000.00 B, DR 5-20%, FM, HEAVY ROOTS
S-MA20012034		1ST MH N.OF LOGAN AV(E.OF CL) TO MH AT LOGAN AV.	CS	300 CLAY	4 EXTERNAL PT REPAIR		82.7		\$22,000.00 SMW
S-MA20000151		1ST MH N.OF CARON TO MH AT CARON AV	LDS	375 CONCRETE	5 EXTERNAL PT REPAIR		30.7		\$15,000.00 SMW, FM, FL, FC, JSL
		MH AT ASHBURN ST(W.PL) TO MH AT ASHBURN ST(CL)	CS	750 CONCRETE	5 FULL SEGMENT RENEWAL		0		\$53,400.00
									MISSING PIPE WITH VOIDING SEEN IN MANHOLE INSPECTION FOR
									S-MH20015862. NO CCTV INSPECTION FOR S-MA70009252
									COMPLETED. VOIDING IS APPROX. 0.52M FROM MANHOLE WALL.
S-MA70009252	YARWOOD AV	MH AT SHERBURN ST TO PLUG	LDS	300 CONCRETE	5 EXTERNAL PT REPAIR		38.583	2	COMPLETED. VOIDING IS APPROX. 0.52M FROM MANHOLE WALL. \$15,000.00 EXTENT COULD BE GREATER.