


### Fall Inspections

#### LEGEND

- CS
- LDS
- WWS
- CB Lead
- SEWER MANHOLE
- CATCH BASIN

**SITE CONSIDERATIONS:**  
 ACCESS TO ST. CHARLES COUNTRY CLUB REQUIRED. ACCESS VIA CAR PARK TO THE NORTH OF THE CLUB HOUSE. MANHOLE LOCATED WITHIN WOODED AREA.



Issue Status: Tender

Outfall Asset Number: S-MA20002806 - 96.32m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 623477.3546E, 5525538.4691N

Location: 100 COUNTRY CLUB



Drawing: 225