Photographs of Grit Aeration Unit No. 1
(taken December, 2010 when unit was out of service)








Baffle Item 17


Baffle Item 17 from above


inlet sluice gate
grit residual

Eductor hanger support
channels to be replaced

Sludge draw off pipe Item 19



Baffle Item 17


Baffle Item 17