



Derek Clarke, Drinking Water Officer  
Office of Drinking Water, Manitoba Sustainable Development  
Box 6000  
Gimli, MB R0C 1B0

November 4, 2019

**RE: CORRECTIVE ACTION REPORT FOR WINNIPEG PUBLIC WATER SYSTEM, 252.00**

**Incident No:** CAR\_07-2019

**Reported to ODW:** July 20, 2019

**Reported by:** Bill Laudinsky, Supervisor Maintenance Water

**Approved by:** Zeljko Bodiroga, Water Distribution Engineer

**Incident Date:** July 18, 2019

**Incident Location:** Winnipeg 3-Dist (WM Repair)

**Incident Type:**

1. Low Positive Total Coliform (<10 per100mL), 3 MR 41/2007

**Description of Corrective Actions:**

Water Services:

Immediately made contact with ODW and Environmental Standards, flushed the isolated area and re-sampled original location. Tested the original location for bacteria, turbidity, and free chlorine until two consecutive negative bacteria results were obtained.

**Test Results:** See attached

**LIMS Reference No:** n/a

**EMERGENCY REPORTING IS REQUIRED WHERE A POTENTIAL HEALTH RISK IS INVOLVED. FOLLOW THE INSTRUCTIONS OF YOUR DRINKING WATER OFFICER IN SITUATIONS REQUIRING IMMEDIATE REPORTING**

N:\Environmental Standards\Analytical Services\Government Agencies\Office of Drinking Water\Corrective Action Reports



Water and Waste Department • Service des eaux et des déchets

Sample Name	Work Order Number	Lab Number	Date Sampled	E Coli (MPNU/100mL)	Total Coliform (MPNU/100mL)	Free Chlorine (mg/L)	Turbidity-field (ntu)	Time Sampled (hrs)
Hydrant_Water Main Repair	1909103	L2313490-1	18-Jul-19	<1	2	0.57	2.58	17:00
Hydrant_Water Main Repair (Resample)	1909103	L2313982-1	20-Jul-19	<1	<1	0.66	2.82	19:15
Hydrant_Water Main Repair (Resample 2)	1909103	L2313983-1	21-Jul-19	<1	<1	0.58	0.71	8:20

NOTES/COMMENTS:

1. All microbiological tests performed by contract laboratory.
2. N/R-No Result due to laboratory/analyst error.
3. N/A-Not Analyzed.