

440-2015 ADDENDUM 1

REQUEST FOR PROPOSAL FOR PROFESSIONAL CONSULTING SERVICES FOR THE INSPECTION OF ASBESTOS CONTAINING MATERIAL

URGENT

PLEASE FORWARD THIS DOCUMENT TO WHOEVER IS IN POSSESSION OF THE REQUEST FOR PROPOSAL ISSUED: May 22, 2015 BY: Jennifer Coey TELEPHONE NO. (204) 794-3091

THIS ADDENDUM SHALL BE INCORPORATED INTO THE REQUEST FOR PROPOSAL AND SHALL FORM A PART OF THE CONTRACT DOCUMENTS

Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Request for Proposal, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 9 of Form A: Proposal may render your Proposal non-responsive.

PART D - SUPPLEMENTAL CONDITIONS

Revise:	D4.1 to read:	The Work to be done under the Contract shall consist of the provision of services for asbestos inspections/re-inspections, with additional recommended repairs and risk assessments approved by the Project Manager, at all City of Winnipeg Water and Waste facilities identified in D4.5. This contract has the option of five (5) mutually agreed upon one (1) year extensions.
Revise:	D4.5.1(c)(i) to read:	Barker Standby Generator Building at Daly Gardens Park off Southboine Drive (Original construction: 1981)
Revise:	D4.5.1(f)(i) to read:	Ash Flood Pumping Station at 1055 Wellington Crescent (Original Construction: 1954)
Revise:	D4.5.1(g)(i) to read:	Barker Lift Station at 50 Barker Boulevard (Original construction: 1966)
Revise:	D4.5.1(g)(ii) to read:	Burrows Lift Station at Tyndall Park off Burrows Avenue (Original construction: 1974)
Revise:	D4.5.1(g)(iii) to read:	Clarence Lift Station at the corner of Clarence Avenue and Hamelin Street (Original construction: 1962)
Revise:	D4.5.1(g)(iv) to read:	Grandmont Lift Station at Grandmont Park off Grandmont Boulevard (Original construction: 1981)
Revise:	D4.5.1(g)(v) to read:	Heritage Lift Station at Sturgeon Creek Park off the back lane of 3139 Ness Avenue (Original construction: 1961)
Revise:	D4.5.1(g)(vi) to read:	King Edward Lift Station at the corner of King Edward Street and William Avenue West (Original construction: 1958)
Revise:	D4.5.1(g)(vii) to read:	Mager Lift Station at 13 Mager Drive West (Original construction: 1936)
Revise:	D4.5.1(g)(viii) to read:	Manitoba Lift Station at the corner of Manitoba Avenue and King Edward Street (closer to the back lane) (Original construction: 1978)
Revise:	D4.5.1(g)(ix) to read:	Metro Route 90 Lift Station at 250 Parklane Avenue (Original construction: 1982)
Revise:	D4.5.1(g)(x) to read:	Parklane Lift Station at 132 Parklane Avenue (Original construction: 1963)
Revise:	D4.5.1(g)(xi) to read:	Pulberry Lift Station at 105 St. Vital Road (Original construction: 1959)

RFP No. 440-2015 Addendum 1 Page 2 of 2

Revise:	D4.5.1(g)(xii) to read:	St. Charles Lift Station at the corner of Sansome Avenue and Gagnon Street (Original construction: 1992)
Revise:	D4.5.1(g)(xiii) to read:	Tuxedo Lift Station at Tuxedo Park off Cuthbertson Avenue (Original construction: 1987)
Revise:	D4.5.1(g)(xiv) to read:	Wexford Lift Station at 82 Wexford Street down the back lane (Original construction: 1963)
Revise:	D4.5.3 to read:	Conduct interior and exterior visual inspections, including roof , and take digital photographs of all known or suspected ACM locations.
Revise:	D4.5.3(d) to read:	Notify the Project Manager of any ACM requiring immediate remedial action. Maintain a detailed log of all locations requiring corrective actions to be taken. Provide material testing, air monitoring, safe work practices and other services if required. Provide the Project Manager with a risk assessment of each location in a timely matter.
Add:	D8.2(a)(v) to read:	Certificates of insurance to indicate the consultants operations include asbestos inspection and risk assessment services.

APPENDIX C

Add: 440-2015_Addendum1-Appendix_C-2014_Asbestos_Survey_Updates.