

A

repairs as per SK-13

new finger joints  
(full width)


4" min

4" min

new 2x12 wood laminations  
(trimmed to 11" width)  
c/w  
epoxy glue resin between  
wood laminations

New Glulam Beam Repair Methods

Scale: 1" = 1'-0"



# SK-6

Glulam Beam Repairs  
Roland Michener Arena  
1121 Wabasha Street  
Winnipeg, MB R2C 1G6



**GC ENGINEERING LTD.**  
675 ELM ST.  
WINNIPEG MB R3M 3N8  
PH 793-3948 FAX 487-4616  
EMAIL CALGRAY@MTS.NET