



## 609-2009 ADDENDUM 2

### WATER PUMPING STATIONS ELECTRICAL INSPECTIONS

#### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO  
WHOEVER IS IN POSSESSION OF THE BID  
OPPORTUNITY**

ISSUED: September 10, 2009  
BY: Curtis Reimer  
TELEPHONE NO. (204) 786-8080

**THIS ADDENDUM SHALL BE INCORPORATED  
INTO THE BID OPPORTUNITY AND SHALL  
FORM A PART OF THE CONTRACT  
DOCUMENTS**

Template Version: A20070419

---

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.**

---

#### **PART E – SPECIFICATIONS**

Revise: E9.5(a)(ii) to read: (ii) Install within the existing cases for the A, C, and N relays.

Clarification of E9.5(a): There are existing relays/cases for phases A, C, and N. The new relays for phases A, B and C shall be installed into the existing cases and a new cutout and case installed for the new N relay. See reference drawing 1-0640M-E0015 for clarification.

Revise: E10.5 (a) to read: (a) Phase A, C and N overcurrent relays:

Revise: E10.5 (a)(ii) to read: (ii) Install within the existing cases for the A, C, and N relays.

Clarification of E10.5: There are existing relays/cases for phases A, C, and N. The new relays for phases A, C and N shall be installed into the existing cases and a new case installed in the existing cutout for the 27 relay, which will be removed. See reference drawing 1-0630M-E0013 for clarification.

Delete: E11.4(f)

Revise: E12 (c) to read: Utilize the existing drawings for reference while performing the specified electrical inspection work. Where the existing installation deviates from that shown on the drawings, mark-up the drawings as required to reflect the installation.

Add: E12(c)(i) The scope of required drawing checks is limited to the equipment and components that are part of the electrical inspection work.

Add: E12(c)(ii) Any repairs made that affect the accuracy of the drawings shall be marked up on the drawings.

Clarification of E36: The 600V air circuit breakers do not have electronic relays.