



## 487-2012 ADDENDUM 1

### NEWPCC SECONDARY CLARIFIERS 7 TO 10 REHABILITATION

#### **URGENT**

**PLEASE FORWARD THIS DOCUMENT TO  
WHOEVER IS IN POSSESSION OF THE BID  
OPPORTUNITY**

ISSUED: August 21, 2012  
BY: **Colin Siepman, P.Eng.**  
TELEPHONE NO. (204) 896-1209

**THIS ADDENDUM SHALL BE INCORPORATED  
INTO THE BID OPPORTUNITY AND SHALL  
FORM A PART OF THE CONTRACT  
DOCUMENTS**

Template Version: A20120228

---

**Please note the following and attached changes, corrections, additions, deletions, information and/or instructions in connection with the Bid Opportunity, and be governed accordingly. Failure to acknowledge receipt of this Addendum in Paragraph 8 of Form A: Bid may render your Bid non-responsive.**

---

#### **PART A – BID SUBMISSION**

Replace: 487-2012 Bid Submission with 487-2012 Addendum 1- Bid Submission. The following is a summary of changes incorporated in the replacement Bid Submission:

Form B(R1): Quantity of item number 3 (Wear Plate Replacement) has been revised.

Form B(R1): Item 4 description has been revised to "Wear Plate Coating and Recoating."

#### **PART E – SPECIFICATIONS**

Add: E10.10(f) Placards at the Work area perimeter designating a dust environment area shall be clearly visible and displayed during all abrasive blast cleaning operations. Dust containment and control measures are not required. Cleanup of dust caused by abrasive blast cleaning outside the limits of secondary clarifiers 7 to 10 is not required.

Revise: E12.4(b) to read: Wear plate coating and recoating will be measured on a linear meter basis and paid for at the Contract Unit Price for "Wear Plate Coating and Recoating." Said price shall be payment in full for supplying all materials and performing all operations herein described and all other items incidental to the work included in this specification.