

Fall Inspections


LEGEND

- ▶ LDS
- ▶ WWS
- SEWER MANHOLE

SITE CONSIDERATIONS:

KEY CONTACTS:

AFFECTED RESIDENTS:
2065 HENDERSON HWY



Issue Status: Tender



Drawing: 19

Outfall Asset Number: S-MA40000284 - 25.82m

Upstream Sewer Asset Number: None - 0m

Upstream Manhole Coordinates: 638458.7552E, 5535851.0618N

Location: 2075 HENDERSON HWY