
NOTES:

- 1. BACKFILL UNDER PAVEMENT, IN SIDEWALKS, & WITHIN 1.0 m OF PAVEMENT TO BE CLASS 3.
- 2. CONFIRM LIMITS OF REPAIR IN PRESENCE OF THE CONTRACT ADMINISTRATOR BY CCTV.



NO. REVISIONS

SEWER JUNCTION INFORMATION FROM SEWER VIDEO INSPECTION S-MA20005788					
	DISTA	ANCE FROM	MH S-MH2	20005321	
47.9	S	150ø	WEST	CXI	
48.7	S	150ø	EAST	CXI	
61.0	S	150ø	WEST	CXI	
91.6	S	150ø	WEST	CX	
93.2	S	150ø	EAST	CX	
				·	

07/09/10

ORIGINAL SIGNED BY K.R. ZUREK

CONTRACT 16

FILENAME: 06176.dwg PLOT DATE: 2007 09 10

B.M. FIELD BOOK #: POSTED TO LBIS DESIGNED NC CHECKED TW/KZ DEAWN CJH APPROVED KZ HOR. SCALE 1:500 RELEASED FOR CONSTRUCTION

DATE



THE CITY OF WINNIPEG WATER AND WASTE DEPARTMENT

SHEET 18 OF 25

06176

CITY DRAWING NUMBER

2007 SEWER RENEWALS AND REPAIRS
CONTRACT 16

WALLASEY STREET
MH AT LODGE AVENUE TO
1ST MH S OF LODGE AVENUE

LEGEND:

52.0 | Measurement to repair from reference mh shown thus... METRIC
WHOLE NUMBERS INDICATE MILLIMETRES
DECIMALIZED NUMBERS INDICATE METRES