Template Version: C420171218 - RW

# APPENDIX 'B' PAVEMENT CORE REPORT

Template Version: C420171218 - RW

### APPENDIX 'B' - PAVEMENT CORE REPORT

### **TABLE OF CONTENTS**

Test Hole Locations	2
Summary of Core Samples	3
Pavement Core Photos	4

The pavement core report is provided to aid in the Contractor's evaluation of the existing pavement structure and/or soil conditions. The information presented is considered accurate at the locations shown on the Drawings and at the time of drilling. However, variations in pavement structure and/or soil conditions may exist between test holes and fluctuations in groundwater levels can be expected seasonally and may occur as a result of construction activities. The nature and extent of variations may not become evident until construction commences.

## **Test Hole Locations**

## Pavement Core Location Plan Pembina Highway Northbound, Ducharme Avenue to Cloutier Drive



Image obtained from Stantec Consulting Ltd. Geotechnical Report (Image source: Google Earth)

Template Version: C420171218 - RW

## **Summary of Core Samples**



## TABLE 1 PEMBINA HIGHWAY FROM CLOUTIER DRIVE TO DUCHARME AVENUE CORING INVESTIGATION

Testhole ID	Testhole Location	Pavement Surface		Pavement Structure Material	
		Туре	Thickness (mm)	Туре	Thickness (mm)
THO1	Pembina Highway Northbound curb lane, 50 m north of Ducharme Avenue 1 m west of curb	Asphalt	50	Concrete	220
TH02	Pembina Highway Northbound median lane, 165 m north of Ducharme Avenue, 1 m east of curb	Asphalt	130	Concrete	210
TH03	Pembina Highway Norhtbound curb lane, 35 m South of Grandmont Blvd 1.0 m west of curb	Asphalt	25	Concrete	185
TH04	Pembina Highway Northbound curb lane, 58 m north of Grandmont Blvd 1.0 m west of curb	Asphalt	35	Concrete	215
TH05	Pembina Highway Northbound curb lane, 170 m north of Grandmont Blvd 1.0 m west of curb	Asphalt	50	Concrete	185
TH06	Pembina Highway Northbound median lane, 95 m south of Cloutier Dr 2.0 m east of curb	Asphalt	90	Concrete	145
TH07	Pembina Highway Northbound median lane, 20 m south of Cloutier Dr 2. 0 m east of curb	Asphalt	90	Concrete	205

## **Pavement Core Photos**






Photo 1 - TH01 Core



Photo 2 - TH02 Core






Photo 3 – TH03



Photo 4 - TH04






Photo 5 - TH05



Photo 6 - TH06





Photo 7 - TH07