


Survey Grades in This Area  
 Are No Longer Valid Due  
 To Disturbed Conditions

**NOTES**

This survey was done by MMM Group in 2016 prior to the construction of a gravel parking lot.

The elevations have not been corrected to Geodetic Elevations.

The Contractor shall be responsible for establishing a Bench Mark and verifying the elevations required to grade the Site.



Location of underground structures as shown are based on the best information available but no guarantee is given that all existing utilities are shown or that the given locations are exact. Confirmation of existence and exact location of all services must be obtained from the individual utilities before proceeding with construction.

DO NOT SCALE DRAWING - PLOT MAY NOT BE AT 100%

9			
8			
7			
6			
5			
4			
3			
2			
1			

NO. REVISION / NOTE DATE BY

PROJECT

PR RESTORATION  
 409 MULVEY AVENUE  
 WINNIPEG, MANITOBA

SCALE 1:200

DATE NOVEMBER 9, 2021

DRAWN BY LLW PROJECT NO. 2116

CHECKED BY DW

DRAWING TITLE

SURVEY 2016  
 PRE PARKING LOT

SHEET NO.