



*Figure 1 Streetcar Track Bedding below existing pavement (Station 2+360).*



*Figure 2 Streetcar Track Bedding below existing pavement (Station 2+360). The track bedding thickness measured 0.45m at this location.*



*Figure 3 Streetcar Track Bedding below existing pavement (Station 2+360). Note previous wooden tie location.*