



REMOVE PAINT & REPAINT CEILING

REPAIR L FRAMING AT ACCESS -

REPAIR CONC. WALL -

GALV. W250x38 HOIST BEAM C/W 12 mm Ø HAS E B7 DRILLED & EPOXIED INTO CONC. SLAB WITH HILTI

PROVIE 100 MIN. EMBED. @ 102 O/C STAGGERED

HOIST BEAM MARK "1 TON" C/W LOW HEADROOM PROFILE GEAR TROLLEY HOIST MOUNT 1 TON CAPACITY WITH 20 FT. LIFT, 10 FT. HAND CHAIN.

(SHB010 OR VULCAN OR APPROVED EQUIVALENT.)

- END 10 PL STIFFENERS

EACH SIDE

HIT-HY 200

NEW OPENING IN SLAB

FILL HOLES WITH HIGH

STRENGTH GROUT -

- REMOVEABLE RAIL,

150 1306+/-

B

- NEW 150 mm Ø OPENINGS

IN SLAB. TO BE VERIFIED

S-09

WITH PROCESS DRAWINGS