














 **THE CITY OF WINNIPEG**  
**WATER AND WASTE DEPARTMENT**

**Bid Opportunity No. 240-2014**  
**2014 SEWER CONDITION ASSESSMENT**

**IDENTIFIERS AND SIZES**

Legend

 RE-INSPECTIONS	 SEWER MAIN
 RE-INSPECTIONS - MISSING VIDEO	 WWS SEWER MAIN
 WASTEWATER SEWER INSPECTIONS	 LDS SEWER MAIN
 STORM RELIEF SEWER INSPECTIONS	 SEWER MANHOLE
 TRUNK SEWER INSPECTIONS	 WHITE CAPPED HYDRANTS
 SYNERGEN TROUBLE SEWER	 POSSIBLE WEIR LOCATION
 SEWER MANHOLE (TO BE INSPECTED)	 SEWER PUMP STATION
 WEIR MANHOLE (TO BE INSPECTED)	

**ASSET TYPE IDENTIFIERS**  
SEWERMAIN: M-----  
MANHOLE: M-----  
TEE: T-----  
PLUGS: PL-----

MAP 1 **AECOM** REVISION 0  
21/03/2014

