888-2015\_251\_Donald\_Elevator\_No\_06\_Improvement\_Order\_MB\_Elevator\_No\_6015-R00
Office of the Fire

Commissioner

Inspection and Technical Services Winnipeg Office: 508-401 York Avenue Winnipeg, Manitoba, Canada R3C 0P8 Phone: 204



Elevator/Amusement Ride Inspection Report / Order to Remedy					
6015			Owner! #: CITY of Winnipeg		
251 Donald			Contact Name/Phone/Email:  Device Name/Number:		
COMMENTS: Passinger Elevator					
Code being enforced: ☐ B44 ☐ B355 ☐ C22.1 ☐ Z267 ☐ Z98 ☐ Z185					
The following deficiencies have been identified and require the following corrective action(s) to be completed by the noted compliance date.					
No.	Code Reference/ Article No.	Deficiency	Corrective Action	Compliance Date	
	9	Repair The emergency Light and alarm in		2016	
	CD	Repair The car door restrictor and it shull be made to work at all Times			
	CD 06	The gap between the cer door and cardoor Jam shall be Less Than 10mm			
	He 15	Install missing ut Thru roller on main floor	57		
	02	Rapair the abarm bel	(	30	
***Additional information as required may be made on additional pages, and shall become part of this inspection report  Number of Additional Pages Attached:					
MG-16004 (Rev. 05/15)					

Inspection Comments/Recommendations:					
	-	· · · · · · · · · · · · · · · · · · ·			
4177411	The second secon				
Applicable Fees Fo	or Re inspection Due To Order(s)	(As Per Elevator/Amusements Acts and Regulations)			
	Annala	f Ouder(c)			
Appeal of Order(s)					
The person to whom the indicated order(s) has been directed to may submit a request for appeal of the order(s) to the Director.					
The request must be in writing and must include:					
(a) The person's name and address and the reasons for requesting the appeal; and (b) A copy of the order.					
A request for appeal of an order must be made within the following times:					
<ul><li>(a) If the order requires compliance in less than 14 days, within the time specified for compliance.</li><li>(b) In any other case, within 14 days after the person received or is deemed to have received the order.</li></ul>					
Date:					
Inspector Name:					
Inspection Address:	251 Donald Car	Itennial Library EL + #6			
Phone Number:					
Report provided to:					

888-2015\_251\_Donald\_Elevator\_No\_06\_Improvement\_Order\_MB\_Elevator\_No\_6015-R00

This report has been prepared for the above named client for the purposes of performing an inspection of the equipment named. The report is solely based on conditions existing on the above noted inspection date. No representation or responsibility is assumed whatsoever to third parties who rely on this report without authorization. The Owner or their Authorized Agent shall be solely responsible for ensuring that out the provisions in the Elevator/Amusements Act and Regulations are carried out.