

APPENDIX 'B'


EXISTING SITE PHOTOGRAPHS



Photograph 1. Refueling Area ↑



Photograph 2. Damaged Spill Containment Manhole ↑



Photograph 3. Damaged Tank Turbine and Sensor ↑



Photograph 4. Installation of Underground Storage Tank & Liner ↑



Photograph 5. Installation of Underground Storage Tank & Liner ↑



Photograph 6. Installation of Underground Storage Tank & Liner ↑



Photograph 7. Installation of Underground Storage Tank & Liner ↑