


INVESTIGATE OUTFALL LOCATION





COMBINED SEWER CONNECTION AT TACHE/ HEBERT HAS BEEN CUT OFF


 THE CITY OF WINNIPEG
WATER AND WASTE DEPARTMENT

Request for Proposal No. 61-2020
2019 BRANCH I AQUEDUCT UNDERDRAIN
CONDITION ASSESSMENT

IDENTIFIERS AND SIZES

Legend

 AQUEDUCT UNDERDRAIN (to be cleaned and inspected)	 SEWER MAIN
 AQUEDUCT	 WWS SEWER MAIN
 UNDERDRAIN MANHOLE (to be cleaned and inspected)	 LDS SEWER MAIN
	 SEWER MANHOLE

MAP 05  REVISION 0
15/01/2020

- ASSOCIATED AS-BUILT RECORDS**
- D-6300
 - D-6301
 - D-6274
 - D-2166
 - D-6275
 - D-6276
 - D-14546
 - D-6302
 - D-6303
 - D-6304
 - D-6305
 - D-6306
 - D-6307

