



**Request for Proposal No. 61-2020
2019 BRANCH I AQUEDUCT UNDERDRAIN
CONDITION ASSESSMENT**

IDENTIFIERS AND SIZES

Legend

	AQUEDUCT UNDERDRAIN (to be cleaned and inspected)		SEWER MAIN
	AQUEDUCT		WWS SEWER MAIN
	UNDERDRAIN MANHOLE (to be cleaned and inspected)		LDS SEWER MAIN
			SEWER MANHOLE

**ASSOCIATED
AS-BUILT RECORDS**

D-6368
D-6369
D-6370
D-6371
D-6372
D-6373

